DTC P2855:00 [TCM (EW6A-EL)]

id0502p7578600

DTC P2855:00	**Low clutch hydraulic circuit/sealing malfunction**
DETECTION CONDITION	• Slow engaging after operating selector lever from N to D position.
FAIL-SAFE FUNCTION	Not applicable
POSSIBLE CAUSE	• Low clutch piston sealing malfunction • Seal ring poor functioning • ATF is less than specified value
SYSTEM WIRING DIAGRAM	Not applicable

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**INSPECT ATF LEVEL** • Inspect the ATF level. (See AUTOMATIC TRANSAXLE FLUID (ATF) INSPECTION [EW6A-EL].) • Is there any malfunction?	Yes	Adjust the ATF level to the specification, then go to the next step. (See AUTOMATIC TRANSAXLE FLUID (ATF) ADJUSTMENT [EW6A-EL].)
		No	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [EW6A-EL].)
2	**VERIFY DTC TROUBLESHOOTING COMPLETED** • Perform the following procedure to ensure that the DTC has been resolved: 1. Verify that the ATF temperature is **30 °C {86 °F} or more**. 2. Perform the following operation **20 times**. — Operate the selector lever from N to D position and wait for **5 s or more**. — Operate the selector lever from D to N position and wait for **5 s or more**. • Clear the DTC using the M-MDS. (See ON-BOARD DIAGNOSTIC SYSTEM DTC INSPECTION [TCM (EW6A-EL)].) • Perform the DTC inspection using the M-MDS. (See ON-BOARD DIAGNOSTIC SYSTEM DTC INSPECTION [TCM (EW6A-EL)].) • Is the DTC P2855:00 present?	Yes	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [EW6A-EL].)
		No	DTC troubleshooting completed.