## DTC P0729:00 [TCM (EW6A-EL)]

id0502p7822000

| DTC P0729:00 | 6GR incorrect ratio |
|---|---|
| DETECTION CONDITION | • In D position, 6GR, the following phenomenon occurs:<br>— There is difference between turbine/input shaft speed and output shaft speed sensor speed for **230 to 1,980 ms** (varies with ATF temperature and ECT) during shift-up.<br>— There is difference between turbine/input shaft speed and output shaft speed sensor speed for **1,500 to 3,900 ms** (varies with ATF temperature) while driving without shifting. |
| FAIL-SAFE FUNCTION | • Inhibits malfunctioning gear.<br>• Limits engine torque.<br>• Inhibits learning control.<br>• Inhibits manual mode.<br>• Inhibits neutral idle control.<br>• Inhibits i-stop control.<br>• Inhibits AAS. |
| POSSIBLE CAUSE | • ATF is less than specified value<br>• Clutch burnt<br>• Shift solenoid malfunction<br>• ATF leakage from clutch circuit<br>• Control valve body malfunction |
| SYSTEM WIRING DIAGRAM | Not applicable |

### Diagnostic procedure

| STEP | INSPECTION | | ACTION |
|---|---|---|---|
| 1 | **VERIFY DTC OUTPUT STATUS**<br>• Are any the following DTCs displayed?<br>— P0746:00, P0751:00, P0752:00, P0756:00, P0757:00, P0761:00, P0762:00, P0766:00, P0767:00, P0771:00, P0772:00, P0842:00, P0843:00, P0847:00, P0848:00, P0872:00, P0873:00, P0877:00, P0878:00, P1784:00 | Yes | Go to the applicable DTC inspection.<br>(See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE [TCM (EW6A-EL)].) |
| | | No | Go to the next step. |
| 2 | **INSPECT ATF LEVEL**<br>• Inspect the ATF level.<br>(See AUTOMATIC TRANSAXLE FLUID (ATF) INSPECTION [EW6A-EL].)<br>• Is there any malfunction? | Yes | Adjust the ATF level to the specification, then go to the next step.<br>(See AUTOMATIC TRANSAXLE FLUID (ATF) ADJUSTMENT [EW6A-EL].) |
| | | No | Go to the next step. |
| 3 | **PERFORM ON-BOARD DIAGNOSTIC TEST TO SPECIFY MALFUNCTIONING PART**<br>• Perform the on-board diagnostic test.<br>(See ON-BOARD DIAGNOSTIC TEST MODE [TCM (EW6A-EL)].)<br>• Are any DTCs present? | Yes | Go to the applicable DTC inspection.<br>(See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE [TCM (EW6A-EL)].) |
| | | No | ATF amount in Step 2 is correct:<br>• Replace the automatic transaxle.<br>(See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [EW6A-EL].)<br>ATF amount adjusted in Step 2:<br>• Drive the vehicle to check it, and if there is no problem then the DTC troubleshooting is complete. |