DTC P0C2C:00 [TCM (EW6A-EL)]

id0502p7832600

DTC P0C2C:00	**Electric AT oil pump mechanical malfunction**
DETECTION CONDITION	• The actual electric AT oil pump rotation speed under the following conditions is **100 rpm or less** for a continuous **10 s**: — Electric AT oil pump rotation speed command value is **500 rpm or more**. — Electric AT oil pump relay is ON. — DTC P181F:00 and P0C2D:00 are not recorded.
FAIL-SAFE FUNCTION	• Inhibits i-stop control.
POSSIBLE CAUSE	• Electric AT oil pump malfunction • Short to ground or open circuit in wiring harness between battery positive terminal and electric AT oil pump terminal D
SYSTEM WIRING DIAGRAM	Not applicable

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**VERIFY RELATED SERVICE INFORMATION AVAILABILITY** • Verify related Service Information availability. • Is any related Service Information available?	Yes	Perform repair or diagnosis according to the available Service Information. • If the vehicle is not repaired, go to the next step.
		No	Go to the next step.
2	**INSPECT ELECTRIC AT OIL PUMP POWER SUPPLY CIRCUIT FOR SHORT TO GROUND OR OPEN CIRCUIT** • Verify that the electric AT oil pump connector is disconnected. • Switch the electric AT oil pump relay to ON using the simulation item EOP_RLY. (See ON-BOARD DIAGNOSTIC SYSTEM SIMULATION INSPECTION [TCM (EW6A-EL)].) • Measure the voltage at the electric AT oil pump terminal D (wiring harness-side). • Is the voltage 0 V?	Yes	Refer to the wiring diagram and verify whether or not there is a common connector between battery positive terminal and electric AT oil pump terminal D. **If there is a common connector:** • Determine the malfunctioning part by inspecting the common connector and the terminal for corrosion, damage, or pin disconnection, and the common wiring harness for a short to ground or open circuit. • Repair or replace the malfunctioning part. **If there is no common connector:** • Repair or replace the wiring harness which has a short to ground.
		No	Go to the next step.
3	**REPLACE ELECTRIC AT OIL PUMP AND VERIFY THAT MALFUNCTION IS RESOLVED** • Replace the electric AT oil pump. (See ELECTRIC AT OIL PUMP REMOVAL/INSTALLATION [EW6A-EL].) • Clear the DTC using the M-MDS. (See ON-BOARD DIAGNOSTIC SYSTEM DTC INSPECTION [TCM (EW6A-EL)].) • Perform the DTC inspection using the M-MDS. (See ON-BOARD DIAGNOSTIC SYSTEM DTC INSPECTION [TCM (EW6A-EL)].) 1. Operates the i-stop. • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE [TCM (EW6A-EL)].)
		No	DTC troubleshooting completed.