ABNORMAL SHIFTING [CW6A-EL]

id050321101200

TROUBLESHOOTING ITEM	Abnormal shifting
DESCRIPTION	• Shifts incorrectly (incorrect shift pattern).
POSSIBLE CAUSE	1. Signal malfunction — APP sensor malfunction — BARO sensor malfunction — Brake switch malfunction — CKP sensor malfunction — ECT sensor No.1 malfunction — IAT sensor No.1 malfunction — MAF sensor malfunction 2. Low-G (XY) sensor (built into SAS control module) malfunction **Note** • When driving on high-altitude roads, the TCM determines that the driving mode is the AAS mode, and may change to a different shift timing from the normal timing. • When SPORT mode is selected with the drive selection system, a lower gear than NORMAL mode is selected, and the gear is maintained for a longer period of time.

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**INSPECT SIGNAL PARTS FOR MALFUNCTION** • Inspect the value at the following PCM PIDs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) — APP (APP sensor) — BARO (BARO sensor) — BOO (Brake switch) — ECT (ECT sensor No.1) — IAT (IAT sensor No.1) — MAF (MAF sensor) — RPM (CKP sensor) • Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Go to the next step.
2	**VERIFY IF MALFUNCTION CAUSE IS LOW-G (XY) SENSOR** • Is there any malfunction?	Yes	Replace the SAS control module. (See SAS CONTROL MODULE REMOVAL/ INSTALLATION [STANDARD DEPLOYMENT CONTROL SYSTEM].) (See SAS CONTROL MODULE REMOVAL/ INSTALLATION [TWO-STEP DEPLOYMENT CONTROL SYSTEM].)
		No	Symptom troubleshooting is completed.