ENGINE FLARES UP OR SLIPS WHEN UPSHIFTING OR DOWNSHIFTING [CW6A-EL]

id050321101700

TROUBLESHOOTING ITEM	Engine flares up or slips when upshifting or downshifting
DESCRIPTION	• When accelerator pedal is depressed, engine speed increases normally but vehicle speed increases slowly. • When accelerator pedal is depressed while driving, engine speed increases but vehicle speed does not.
POSSIBLE CAUSE	1. Insufficient TCM learning 2. Signal malfunction — APP sensor malfunction — CKP sensor malfunction — MAF sensor malfunction

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**VERIFY MALFUNCTION SYMPTOM** • Is the malfunction symptom at the same level compared to a vehicle of the same model?	Yes	Symptom troubleshooting is completed.
		No	Go to the next step.
2	**PERFORM INITIAL LEARNING** • Perform the initial learning. (See INITIAL LEARNING [CW6A-EL].) • Does the symptom disappear?	Yes	Symptom troubleshooting is completed.
		No	Go to the next step.
3	**INSPECT SIGNAL PARTS FOR MALFUNCTION** • Inspect the value at the following PCM PIDs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) — APP (APP sensor) — MAF (MAF sensor) — RPM (CKP sensor) • Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Symptom troubleshooting is completed.