EXCESSIVE SHIFT SHOCK IS FELT WHEN UPSHIFTING AND DOWNSHIFTING [CW6A-EL]

id050321102100

TROUBLESHOOTING ITEM	**Excessive shift shock is felt when upshifting and downshifting**
DESCRIPTION	• Excessive shift shock is felt when depressing accelerator pedal to accelerate at upshifting. • During cruising, excessive shift shock is felt when depressing accelerator pedal at downshifting.
POSSIBLE CAUSE	1. Insufficient TCM learning 2. Signal malfunction — APP sensor malfunction 3. Poor installation or worn of engine mount, suspension

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**VERIFY MALFUNCTION SYMPTOM** • Is the malfunction symptom (shift shock/shifting time) at the same level compared to a vehicle of the same model?	Yes	Symptom troubleshooting is completed.
		No	Go to the next step.
2	**PERFORM INITIAL LEARNING** • Perform the initial learning. (See INITIAL LEARNING [CW6A-EL].) • Does the symptom disappear?	Yes	Symptom troubleshooting is completed.
		No	Go to the next step.
3	**PERFORM ON-BOARD DIAGNOSTIC TO VERIFY HYDRAULIC PRESSURE SWITCH OPERATION PRESSURE** • Is the operation pressure normal?	Yes	Go to the next step.
		No	Replace the control valve body. (See CONTROL VALVE BODY REMOVAL/INSTALLATION [CW6A-EL].)
4	**INSPECT SIGNAL PARTS FOR MALFUNCTION** • Inspect the value at the following PCM PID using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) — APP (APP sensor) • Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Go to the next step.
5	**INSPECT ENGINE MOUNT/SUSPENSION FOR POOR TIGHTENING** • Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result. (See ENGINE REMOVAL/INSTALLATION [SKYACTIV-G 1.3, SKYACTIV-G 1.5].)
		No	Symptom troubleshooting is completed.