EXCESSIVE SHIFT SHOCK ON TORQUE CONVERTER CLUTCH (TCC) [CW6A-EL]

id050321102200

TROUBLESHOOTING ITEM	Excessive shift shock on torque converter clutch (TCC)
DESCRIPTION	• Strong shock is felt when TCC is engaged.
POSSIBLE CAUSE	1. Insufficient TCM learning (Insufficient TCC learning) 2. Signal malfunction — APP sensor malfunction — CKP sensor malfunction 3. Torque converter malfunction

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**PERFORM INITIAL LEARNING AND TCC LEARNING** Perform the initial learning. (See INITIAL LEARNING [CW6A-EL].) Perform TCC learning using the following procedure: (1) The ATF temperature is **20 °C {68 °F} or more**. (2) Constantly maintain the accelerator pedal opening angle between **20%** to **60%**. (3) Accelerate the vehicle from a stop to 1st gear and from 1st to 2nd gear. (4) Perform the shifting above (3) ten times. • Does the symptom disappear?	Yes	Symptom troubleshooting is completed.
		No	Go to the next step.
2	**INSPECT SIGNAL PARTS FOR MALFUNCTION** • Inspect the value at the following PCM PIDs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) — APP (APP sensor) — RPM (CKP sensor) • Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [CW6A-EL].)