JUDDER UPON TORQUE CONVERTER CLUTCH (TCC) OPERATION [EW6A-EL]

id050322101900

TROUBLESHOOTING ITEM	**Judder upon torque converter clutch (TCC) operation**
DESCRIPTION	• Vehicle jolts when TCC is engaged.
POSSIBLE CAUSE	1. Signal malfunction — APP sensor malfunction — CKP sensor malfunction 2. Torque converter malfunction

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**VERIFY MALFUNCTION SYMPTOM** • Is the malfunction symptom at the same level compared to a vehicle of the same model?	Yes	Symptom troubleshooting is completed.
		No	Go to the next step.
2	**INSPECT SIGNAL PARTS FOR MALFUNCTION** • Inspect the value at the following PCM PIDs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) — APP (APP sensor) — RPM (CKP sensor) • Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [EW6A-EL].)