SLOW ENGAGING AFTER OPERATING SELECTOR LEVER FROM N TO D POSITION [EW6A-EL]

id050322104500

TROUBLESHOOTING ITEM	Slow engaging after operating selector lever from N to D position
DESCRIPTION	• When depressing the accelerator pedal just after operating the selector lever from N to D position with the ATF temperature at **60 °C {140 °F} or more**, it takes **3 s or more** to engage. • Malfunction symptom only occurs once when accelerating from a standstill. • Engagement after operating the selector lever from N to R position is normal.
POSSIBLE CAUSE	1. Low clutch piston malfunction 2. Low clutch hydraulic system sealing malfunction

Diagnostic Procedure

Step	Inspection	Results	Action
1	**VERIFY DTCs** • Are any DTCs detected?	Yes	Repair the malfunctioning location according to the applicable DTC troubleshooting. (See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE [TCM (EW6A-EL)].)
		No	Go to the next step.
2	**PERFORM INITIAL LEARNING AND N TO D RANGE LEARNING** 1. Perform the initial learning. (See INITIAL LEARNING [EW6A-EL].) 2. Perform the N to D position learning using the following procedure: (1) Set the ATF temperature to **30 °C {86 °F} or more**. (2) Shift the selector lever to N position. (3) Shift the selector lever to D position and wait for **5 s or more**. (4) Shift the selector lever to N position and wait for **5 s or more**. (5) Perform steps (3) to (4) **10 times**. • Has the malfunction symptom been eliminated?	Yes	Complete the symptom troubleshooting.
		No	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [EW6A-EL].)