DTC C1B00:2F/C1B00:61/C1B00:62 [EPS CONTROL MODULE]

id060230802300

DTC	**C1B00:2F**	**Steering angle sensor**
	C1B00:61	
	C1B00:62	
DETECTION CONDITION		• C1B00:2F — Signal error in steering angle sensor is detected • C1B00:61 — Error in steering angle sensor calculation of steering angle • C1B00:62 — Error in steering angle comparison by steering angle sensor
FAIL-SAFE FUNCTION		• C1B00:2F — Power steering malfunction indicator light does not Illuminate — EPS motor current control enabled • C1B00:61 — Power steering malfunction indicator light Illuminates — EPS motor current control disabled • C1B00:62 — Power steering malfunction indicator light Illuminates — EPS motor current control enabled
POSSIBLE CAUSE		• Steering angle sensor malfunction in steering column
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY EPS CONTROL MODULE DTC** • Using the M-MDS, clear the DTC from the EPS control module. (See CLEARING DTC [EPS CONTROL MODULE].) • Using the M-MDS, perform the EPS control module DTC inspection. (See DTC INSPECTION [EPS CONTROL MODULE].) • Is the same DTC present?	Yes	Replace the steering column. (See STEERING WHEEL AND COLUMN REMOVAL/ INSTALLATION.)
		No	Go to the next step.
2	**VERIFY NO DTC IS PRESENT** • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [EPS CONTROL MODULE].)
		No	DTC troubleshooting completed.