DTC C200D:49/U2011:49/U2011:61 [EPS CONTROL MODULE]

id060230802400

DTC	**C200D:49**	**EPS motor**
	U2011:49	
	U2011:61	
DETECTION CONDITION		• C200D:49 — Malfunction detected in internal circuit of EPS motor rotation angle sensor • U2011:49 — Malfunction detected in EPS motor internal circuit • U2011:61 — Error in EPS motor signal calculation
FAIL-SAFE FUNCTION		• C200D:49, U2011:49 — Power steering malfunction indicator light Illuminates — EPS motor current control disabled/control is maintained in the backup control • U2011:61 — Power steering malfunction indicator light Illuminates — EPS motor current control disabled
POSSIBLE CAUSE		• EPS motor malfunction in steering column
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY EPS CONTROL MODULE DTC** • Using the M-MDS, clear the DTC from the EPS control module. (See CLEARING DTC [EPS CONTROL MODULE].) • Using the M-MDS, perform the EPS control module DTC inspection. (See DTC INSPECTION [EPS CONTROL MODULE].) • Is the same DTC present?	Yes	Replace the steering column. (See STEERING WHEEL AND COLUMN REMOVAL/ INSTALLATION.)
		No	Go to the next step.
2	**VERIFY NO DTC IS PRESENT** • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [EPS CONTROL MODULE].)
		No	DTC troubleshooting completed.