DTC U3000:05/U3000:41/U3000:43/U3000:46/U3000:49/U3000:61/U3000:96 [EPS CONTROL MODULE]

id060230802900

DTC	**U3000:05**	**EPS control module**
	U3000:41	
	U3000:43	
	U3000:46	
	U3000:49	
	U3000:61	
	U3000:96	
DETECTION CONDITION		• System malfunction detected by self-diagnosis program of EPS control module
FAIL-SAFE FUNCTION		• U3000:05, U3000:41, U3000:46, U3000:49, U3000:61, U3000:96 — Power steering malfunction indicator light Illuminates — EPS motor current control disabled • U3000:43 — Power steering malfunction indicator light does not Illuminate — EPS motor current control enabled
POSSIBLE CAUSE		• Internal malfunction of EPS control module
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY EPS CONTROL MODULE DTC** • Using the M-MDS, clear the DTC from the EPS control module. (See CLEARING DTC [EPS CONTROL MODULE].) • Using the M-MDS, perform the EPS control module DTC inspection. (See DTC INSPECTION [EPS CONTROL MODULE].) • Is the same DTC present?	Yes	Replace the steering column. (See STEERING WHEEL AND COLUMN REMOVAL/ INSTALLATION.)
		No	Go to the next step.
2	**VERIFY NO DTC IS PRESENT** • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [EPS CONTROL MODULE].)
		No	DTC troubleshooting completed.