DTC U3004:49 [EPS CONTROL MODULE]

id060230811900

DTC	U3004:49	EPS control module
DETECTION CONDITION		• Power relay internal malfunction detected in EPS control module
FAIL-SAFE FUNCTION		• Power steering malfunction indicator light Illuminates • EPS motor current control disabled
POSSIBLE CAUSE		• Power relay malfunction in EPS control module
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY EPS CONTROL MODULE DTC** • Using the M-MDS, clear the DTC from the EPS control module. (See CLEARING DTC [EPS CONTROL MODULE].) • Using the M-MDS, perform the EPS control module DTC inspection. (See DTC INSPECTION [EPS CONTROL MODULE].) • Is the same DTC present?	Yes	Replace the steering column. (See STEERING WHEEL AND COLUMN REMOVAL/ INSTALLATION.)
		No	Go to the next step.
2	**VERIFY NO DTC IS PRESENT** • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [EPS CONTROL MODULE].)
		No	DTC troubleshooting completed.