DTC U0401:00 [EPS CONTROL MODULE]

id060230812200

DTC	U0401:00	CAN communication: signal error from PCM
DETECTION CONDITION		• Error detected in signal from PCM via CAN communication
FAIL-SAFE FUNCTION		• Engine speed signal malfunction — Power steering malfunction indicator light Illuminates — EPS motor current control enabled • Vehicle speed signal malfunction — Power steering malfunction indicator light Illuminates — EPS motor current control is maintained by gradually changing the controlled vehicle speed and setting it to specified speed • i-stop condition signal malfunction — Power steering malfunction indicator light does not Illuminate — EPS motor current control enabled
POSSIBLE CAUSE		• PCM malfunction
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY PCM DTC** • Using the M-MDS, perform the PCM DTC inspection. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See DTC TABLE [SKYACTIV-D 1.5].) DTC troubleshooting completed, then go to the next step.
		No	Go to the next step.
2	**VERIFY DTC TROUBLESHOOTING COMPLETED** • Using the M-MDS, clear the DTC from the EPS control module. (See CLEARING DTC [EPS CONTROL MODULE].) • Using the M-MDS, perform the EPS control module DTC inspection. (See DTC INSPECTION [EPS CONTROL MODULE].) • Is the same DTC present?	Yes	Repeat the inspection from Step1. If the malfunction recurs, replace the PCM, then go to the next step. (See PCM REMOVAL/INSTALLATION [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 1.5].)
		No	Go to the next step.
3	**VERIFY NO DTC IS PRESENT** • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [EPS CONTROL MODULE].)
		No	DTC troubleshooting completed.