DTC U0001:88/U0100:00/U0121:00/U0155:00/U0214:00 [BLIND SPOT MONITORING (BSM) SYSTEM]

id09021o064900

Description	• U0001:88 — Unit communication error (MS-CAN) • U0100:00 — Communication error with PCM • U0121:00 — Communication error with DSC HU/CM • U0155:00 — Communication error with instrument cluster • U0214:00 — Communication error with start stop unit
Detection condition	• U0001:88 — Blind spot monitoring (BSM) control module (LH) detects a CAN bus communication line (MS-CAN) malfunction with the ignition switched ON (engine off or on). • U0100:00 — Blind spot monitoring (BSM) control module (LH) cannot receive the CAN signal from the PCM for **2 s or more** with the ignition switched ON (engine off or on). • U0121:00 — Blind spot monitoring (BSM) control module (LH) cannot receive the CAN signal from the DSC HU/CM for **2 s or more** with the ignition switched ON (engine off or on). • U0155:00 — Blind spot monitoring (BSM) control module (LH) cannot receive the CAN signal from the instrument cluster for **2 s or more** with the ignition switched ON (engine off or on). • U0214:00 — Blind spot monitoring (BSM) control module (LH) cannot receive the CAN signal from the start stop unit for **2 s or more** with the ignition switched ON (engine off or on).
Fail-safe	• U0001:88 — Blind spot monitoring (BSM) system is stopped. • U0100:00 — Blind spot monitoring (BSM) system is stopped. • U0121:00 — Blind spot monitoring (BSM) system is stopped. • U0155:00 — Blind spot monitoring (BSM) system is stopped. • U0214:00 — Blind spot monitoring (BSM) system is stopped.
Possible cause	• Malfunction in CAN bus communication line • Malfunction in CAN communication line between PCM and blind spot monitoring (BSM) control module (LH) — Instrument cluster communication error (vehicle speed signal is not sent via instrument cluster from PCM) • Malfunction in CAN communication line between DSC HU/CM and blind spot monitoring (BSM) control module (LH) — Instrument cluster communication error (yaw rate signal is not sent via instrument cluster from DSC HU/CM) • Malfunction in CAN communication line between instrument cluster and blind spot monitoring (BSM) control module (LH) • Malfunction in CAN communication line between start stop unit and blind spot monitoring (BSM) control module (LH) — Instrument cluster communication error (turn switch signal is not sent via instrument cluster from start stop unit)
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)].) (See FOREWORD [SKYACTIV-D 1.5].)