## DTC U3000:97 [BLIND SPOT MONITORING (BSM) SYSTEM]

id09021o066800

| | |
|---|---|
| **Description** | **Radar sensor sensitivity temporarily decreases depending on various external and environmental factors (Blind spot monitoring (BSM) control module (LH))** |
| **Detection condition** | • Radar sensor sensitivity in blind spot monitoring (BSM) control module (LH) decreases for **5 s or more** with the ignition switched ON (engine off or on). |
| **Fail-safe** | • Blind spot monitoring (BSM) system is stopped. |
| **Possible cause** | • Rear bumper dirt or foreign material (reflective object) is adhered.<br>• Dirt or foreign material (reflective object) on blind spot monitoring (BSM) control module (LH)<br>• Concavity and convexity on the surface of the repaired rear bumper<br>• Blind spot monitoring (BSM) control module (LH) malfunction |
| **System wiring diagram** | Not applicable |

### Diagnostic Procedure

| Step | Inspection | | Action |
|---|---|---|---|
| 1 | **INSPECT REAR BUMPER SURFACE**<br>• Visually inspect the rear bumper surface for the following:<br>— Dirt<br>— Adhered foreign material (reflective object)<br>• Is there any dirt or foreign matter (reflective object) on the surface of the rear bumper? | Yes | Remove dirt or foreign material (reflective object), then go to Step 4. |
| | | No | Go to the next step. |
| 2 | **INSPECT AREA AROUND BLIND SPOT MONITORING (BSM) CONTROL MODULE (LH)**<br>• Visually inspect the area around the blind spot monitoring (BSM) control module (LH) for the following:<br>— Dirt<br>— Adhered foreign material (reflective object)<br>• Is there any dirt or foreign matter (reflective object) around the blind spot monitoring (BSM) control module (LH)? | Yes | Remove dirt or foreign material (reflective object), then go to Step 4. |
| | | No | Go to the next step. |
| 3 | **VERIFY REAR BUMPER REPAIR HISTORY**<br>• Verify if the rear bumper had been repaired or repainted before.<br>• Is the repair or repaint of the rear bumper Mazda genuine? | Yes | Go to the next step. |
| | | No | Replace the rear bumper, then go to the next step.<br>(See REAR BUMPER REMOVAL.)<br>(See REAR BUMPER INSTALLATION.) |
| 4 | **VERIFY THAT REPAIRS HAVE BEEN COMPLETED**<br>• Clear the DTC for the blind spot monitoring (BSM) control module using the M-MDS.<br>(See CLEARING DTC [BLIND SPOT MONITORING (BSM) SYSTEM].)<br>• Drive the vehicle at **30 km/h {19 mph} or more**.<br>• Retrieve the blind spot monitoring (BSM) control module DTCs using the M-MDS.<br>(See DTC INSPECTION [BLIND SPOT MONITORING (BSM) SYSTEM].)<br>• Is the same DTC displayed? | Yes | Replace the blind spot monitoring (BSM) control module (LH), then go to the next step.<br>(See BLIND SPOT MONITORING (BSM) CONTROL MODULE REMOVAL/INSTALLATION.) |
| | | No | Go to the next step. |
| 5 | **VERIFY IF OTHER DTCs DISPLAYED**<br>• Are any other DTCs displayed? | Yes | Repair or replace the malfunctioning part according to the applicable DTC troubleshooting.<br>(See DTC TABLE [BLIND SPOT MONITORING (BSM) SYSTEM].) |
| | | No | DTC troubleshooting completed. |