DTC U0001:88/U0010:88/U0100:00/U0101:00/U0121:00/U0131:00/U0140:00/U0151:00/U0156:00/U0164:00/U0182:00/U0214:00/U0232:00/U0235:00/U023A:00 [INSTRUMENT CLUSTER]

id0902e8053600

Description	• U0001:88 — Module communication error (HS-CAN) • U0010:88 — Module communication error (MS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0131:00 — Communication error with EPS control module • U0140:00 — Communication error with BCM • U0151:00 — Communication error with SAS control module • U0156:00 — Communication error with connectivity master unit (CMU) • U0164:00 — Communication error with climate control unit • U0182:00 — Communication error with auto leveling control module • U0214:00 — Communication error with start stop unit • U0232:00 — Communication error with blind spot monitoring (BSM) control module (LH) • U0235:00 — Communication error with laser sensor • U023A:00 — Communication error with forward sensing camera (FSC)
Detection condition	• U0001:88 — Instrument cluster detects a CAN bus communication line (HS-CAN) malfunction. • U0010:88 — Instrument cluster detects a CAN bus communication line (MS-CAN) malfunction. • U0100:00 — Instrument cluster cannot receive the CAN signal from the PCM. • U0101:00 — Instrument cluster cannot receive the CAN signal from the TCM for **1 s or more**. • U0121:00 — Instrument cluster cannot receive the CAN signal from the ABS HU/CM or DSC HU/CM for **1 s or more**. • U0131:00 — Instrument cluster cannot receive the CAN signal from the EPS control module for **1 s or more**. • U0140:00 — Instrument cluster cannot receive the CAN signal from the BCM for **5 s or more**. • U0151:00 — Instrument cluster cannot receive the CAN signal from the SAS control module for **2 s or more**. • U0156:00 — Instrument cluster cannot receive the CAN signal from the connectivity master unit (CMU) for **5 s or more**. • U0164:00 — Instrument cluster cannot receive the CAN signal from the climate control unit for **5 s or more**. • U0182:00 — Instrument cluster cannot receive the CAN signal from the auto leveling control module for **5 s or more**. • U0214:00 — Instrument cluster cannot receive the CAN signal from the start stop unit for **5 s or more**. • U0232:00 — Instrument cluster cannot receive the CAN signal from the blind spot monitoring (BSM) control module (LH) for **1.5 s or more**. • U0235:00 — Instrument cluster cannot receive the CAN signal from the laser sensor for **1 s or more**. • U023A:00 — Instrument cluster cannot receive the CAN signal from the forward sensing camera (FSC) for **1 s or more**.

Description	• U0001:88 — Module communication error (HS-CAN) • U0010:88 — Module communication error (MS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0131:00 — Communication error with EPS control module • U0140:00 — Communication error with BCM • U0151:00 — Communication error with SAS control module • U0156:00 — Communication error with connectivity master unit (CMU) • U0164:00 — Communication error with climate control unit • U0182:00 — Communication error with auto leveling control module • U0214:00 — Communication error with start stop unit • U0232:00 — Communication error with blind spot monitoring (BSM) control module (LH) • U0235:00 — Communication error with laser sensor • U023A:00 — Communication error with forward sensing camera (FSC)
Fail-safe	• U0001:88 — Not applicable • U0010:88 — Not applicable • U0100:00 — Not applicable • U0101:00 — Not applicable • U0121:00 — Not applicable • U0131:00 — Not applicable • U0140:00 — Not applicable • U0151:00 — Not applicable • U0156:00 — Not applicable • U0164:00 — Not applicable • U0182:00 — Not applicable • U0214:00 — Not applicable • U0232:00 — Not applicable • U0235:00 — Inhibits the smart city brake support control. — Warning message related to the smart city brake support is displayed in the center display. (with center display) • U023A:00 — Not applicable

Description	• U0001:88 — Module communication error (HS-CAN) • U0010:88 — Module communication error (MS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0131:00 — Communication error with EPS control module • U0140:00 — Communication error with BCM • U0151:00 — Communication error with SAS control module • U0156:00 — Communication error with connectivity master unit (CMU) • U0164:00 — Communication error with climate control unit • U0182:00 — Communication error with auto leveling control module • U0214:00 — Communication error with start stop unit • U0232:00 — Communication error with blind spot monitoring (BSM) control module (LH) • U0235:00 — Communication error with laser sensor • U023A:00 — Communication error with forward sensing camera (FSC)
Possible cause	• Malfunction in CAN bus communication line • Malfunction in CAN line between PCM and instrument cluster • Malfunction in CAN line between TCM and instrument cluster • Malfunction in CAN line between ABS HU/CM or DSC HU/CM and instrument cluster • Malfunction in CAN line between EPS control module and instrument cluster • Malfunction in CAN line between BCM and instrument cluster • Malfunction in CAN line between SAS control module and instrument cluster • Malfunction in CAN line between connectivity master unit (CMU) and instrument cluster • Malfunction in CAN line between climate control unit and instrument cluster • Malfunction in CAN line between auto leveling control module and instrument cluster • Malfunction in CAN line between start stop unit and instrument cluster • Malfunction in CAN line between blind spot monitoring (BSM) control module (LH) and instrument cluster • Malfunction in CAN line between laser sensor and instrument cluster • Malfunction in CAN line between forward sensing camera (FSC) and instrument cluster
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)].) (See FOREWORD [SKYACTIV-D 1.5].)