DTC U0001:88/U0100:00/U0101:00/U0121:00/U0151:00/U0155:00/U0214:00/U023A:00 [BCM]

id0902f5073200

Description	• U0001:88 — Module communication error (HS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0151:00 — Communication error with SAS control module • U0155:00 — Communication error with instrument cluster • U0214:00 — Communication error with start stop unit • U023A:00 — Communication error with forward sensing camera (FSC)
Detection condition	• U0001:88 — BCM detects the CAN bus communication line (HS-CAN) malfunction **10 times** continuously with the ignition switched ON (engine off or on). • U0100:00 — BCM could not receive the CAN signal from the PCM for 5 **s or more** with the ignition switched ON (engine off or on). • U0101:00 — BCM could not receive the CAN signal from the TCM for **5 s or more** with the ignition switched ON (engine off or on). • U0121:00 — BCM could not receive the CAN signal from the ABS HU/CM or DSC HU/CM for **5 s or more** with the ignition switched ON (engine off or on). • U0151:00 — BCM could not receive the CAN signal from the SAS control module for **5 s or more** with the ignition switched ON (engine off or on). • U0155:00 — BCM could not receive the CAN signal from the instrument cluster for **5 s or more** with the ignition switched ON (engine off or on). • U0214:00 — BCM could not receive the CAN signal from the start stop unit for **5 s or more** with the ignition switched ON (engine off or on). • U023A:00 — BCM could not receive the CAN signal from the forward sensing camera (FSC) for **5 s or more** with the ignition switched ON (engine off or on).

Description	• U0001:88 — Module communication error (HS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0151:00 — Communication error with SAS control module • U0155:00 — Communication error with instrument cluster • U0214:00 — Communication error with start stop unit • U023A:00 — Communication error with forward sensing camera (FSC)
Fail-safe	• U0001:88 **Exterior lighting system** — Turn the TNS and headlights LO on, and turn off other exterior light controls. **Auto light system** — Continue the controls prior to the auto light malfunction detection. **Interior light control system** — Continue the controls prior to the interior light malfunction detection for **5 s** and turn the light on using the initial value after **5 s** have elapsed. **Windshield wiper system** — Continue the controls prior to the windshield wiper malfunction detection. **Front washer system** — Stop the front washer control. **Auto wiper system** — Continue the controls prior to the windshield wiper malfunction detection. **Blower system** — BCM power supply condition is on: Turn the blower relay on. — BCM power supply condition is off: Turn the blower relay off. • U0100:00 **Auto light system** — Continue the controls prior to the auto light malfunction detection. • U0101:00 — Not applicable • U0121:00 — Not applicable • U0151:00 — Not applicable • U0155:00 **Interior light control system** — Continue the controls prior to the interior light malfunction detection for **5 s** and turn the light on using the initial value after **5 s** have elapsed. **Blower system** — BCM power supply condition is on: Turn the blower relay on. — BCM power supply condition is off: Turn the blower relay off. • U0214:00 **Exterior lighting system** — Turn the TNS and headlights LO on, and turn off other exterior light controls. **Auto light system** — Continue the controls prior to the auto light malfunction detection. **Windshield wiper system** — Continue the controls prior to the windshield wiper malfunction detection. **Front washer system** — Stop the front washer control. **Auto wiper system** — Continue the controls prior to the windshield wiper malfunction detection. • U023A:00 — Not applicable

Description	• U0001:88 — Module communication error (HS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0151:00 — Communication error with SAS control module • U0155:00 — Communication error with instrument cluster • U0214:00 — Communication error with start stop unit • U023A:00 — Communication error with forward sensing camera (FSC)
Possible cause	• Malfunction in CAN bus communication line • Malfunction in CAN line between PCM and BCM • Malfunction in CAN line between TCM and BCM • Malfunction in CAN line between ABS HU/CM or DSC HU/CM and BCM • Malfunction in CAN line between SAS control module and BCM • Malfunction in CAN line between instrument cluster and BCM • Malfunction in CAN line between start stop unit and BCM • Malfunction in CAN line between forward sensing camera (FSC) and BCM
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)].) (See FOREWORD [SKYACTIV-D 1.5].)