DTC U2300:55 [HEADLIGHT AUTO LEVELING SYSTEM]

id0902i7017900

Description	Instrument cluster configuration not implemented
Detection condition	• Auto leveling control module received a signal which indicates the instrument cluster configuration is not performed.
Fail-safe	• The headlight leveling actuator is stopped at the position when the malfunction is determined.
Possible cause	**Note** • To correctly write the configuration data sent from the instrument cluster to the auto leveling control module to the auto leveling control module, **30 s or more** need to have elapsed since the ignition was switched ON (engine off or on). • Instrument cluster configuration is not completed. • Auto leveling control module malfunction
System wiring diagram	Not applicable

Diagnostic Procedure

Step	Inspection		Action
1	**RESET CONFIGURATION DATA FROM INSTRUMENT CLUSTER TO AUTO LEVELING CONTROL MODULE** • Clear the DTC for the auto leveling control module using the M-MDS. (See CLEARING DTC [HEADLIGHT AUTO LEVELING SYSTEM].) • Switch the ignition ON (engine off or on) and wait for **30 s or more**. • Retrieve the auto leveling control module DTCs using the M-MDS. (See DTC INSPECTION [HEADLIGHT AUTO LEVELING SYSTEM].) • Is the same DTC displayed?	Yes	Replace the auto leveling control module, then go to the next step. (See AUTO LEVELING CONTROL MODULE REMOVAL/ INSTALLATION.)
		No	Go to the next step.
2	**VERIFY IF OTHER DTCs DISPLAYED** • Are any other DTCs displayed?	Yes	Repair or replace the malfunctioning part according to the applicable DTC troubleshooting. (See DTC TABLE [HEADLIGHT AUTO LEVELING SYSTEM].)
		No	DTC troubleshooting completed.