DTC U0001:88/U0100:00/U0140:00/U0155:00 [HEADLIGHT AUTO LEVELING SYSTEM]

id0902i7073100

Description	• U0001:88 — Unit communication error (HS-CAN) • U0100:00 — Communication error with PCM • U0140:00 — Communication error with BCM • U0155:00 — Communication error with instrument cluster
Detection condition	• U0001:88 — Auto leveling control module detected the CAN bus communication line (HS-CAN) malfunction **10 times** continuously. • U0100:00 — Auto leveling control module could not receive the CAN signal from the PCM for **5 s or more**. • U0140:00 — Auto leveling control module could not receive the CAN signal from the BCM for **5 s or more**. • U0155:00 — Auto leveling control module could not receive the CAN signal from the instrument cluster for **5 s or more**.
Fail-safe	• U0001:88 — The headlight leveling actuator is stopped at the position when the malfunction is determined. • U0100:00 — The headlight leveling actuator is stopped at the position when the malfunction is determined. • U0140:00 — The headlight leveling actuator is stopped at the position when the malfunction is determined. • U0155:00 — Control of the headlight auto leveling system is continued.
Possible cause	• Malfunction in CAN bus communication line • Malfunction in CAN communication line between PCM and auto leveling control module • Malfunction in CAN communication line between BCM and auto leveling control module • Malfunction in CAN communication line between instrument cluster and auto leveling control module
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)].) (See FOREWORD [SKYACTIV-D 1.5].)