DTC U0001:88/U0100:00/U0101:00/U0121:00/U0121:87/U0131:00/U0140:00/U0146:00/U0151:00/U0155:00 [START STOP UNIT]

id0902p6023800

Description	• U0001:88 — Module communication error (HS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0121:87 — Communication error with ABS HU/CM or DSC HU/CM • U0131:00 — Communication error with EPS control module • U0140:00 — Communication error with BCM • U0146:00 — Communication error with BCM • U0151:00 — Communication error with SAS control module • U0155:00 — Communication error with instrument cluster
Detection condition	• U0001:88 — Start stop unit detects the CAN bus communication line (HS-CAN) malfunction **10 times** continuously with the ignition switched ON (engine off or on). • U0100:00 — Start stop unit could not receive the CAN signal from the PCM for **1 s or more** with the ignition switched ON (engine off or on). • U0101:00 — Start stop unit could not receive the CAN signal from the TCM for **1 s or more** with the ignition switched ON (engine off or on). • U0121:00 — Start stop unit could not receive the CAN signal from the ABS HU/CM or DSC HU/CM for **1 s or more** with the ignition switched ON (engine off or on). • U0121:87 — Start stop unit could not receive the CAN signal from the ABS HU/CM or DSC HU/CM for **10 s or more** with the ignition switched off. • U0131:00 — Start stop unit could not receive the CAN signal from the EPS control module for **1.2 s or more** with the ignition switched ON (engine off or on). • U0140:00 — Start stop unit could not receive the CAN signal from the BCM for **5 s or more** with the ignition switched ON (engine off or on). • U0146:00 — Start stop unit could not receive the CAN signal from the BCM for **5 s or more** with the ignition switched ON (engine off or on). • U0151:00 — Start stop unit could not receive the CAN signal from the SAS control module for **1 s or more** with the ignition switched ON (engine off or on). • U0155:00 — Start stop unit could not receive the CAN signal from the instrument cluster for **5 s or more** with the ignition switched ON (engine off or on).

Description	• U0001:88 — Module communication error (HS-CAN) • U0100:00 — Communication error with PCM • U0101:00 — Communication error with TCM • U0121:00 — Communication error with ABS HU/CM or DSC HU/CM • U0121:87 — Communication error with ABS HU/CM or DSC HU/CM • U0131:00 — Communication error with EPS control module • U0140:00 — Communication error with BCM • U0146:00 — Communication error with BCM • U0151:00 — Communication error with SAS control module • U0155:00 — Communication error with instrument cluster
Fail-safe	• U0001:88 — Sets to default signal. — Cancel the i-stop control. (With i-stop system) • U0100:00 — Sets to default signal. — Cancel the i-stop control. (With i-stop system) • U0101:00 — Sets to default signal. • U0121:00 — Sets to default signal. • U0121:87 — Sets to default signal. • U0131:00 — Sets to default signal. • U0140:00 — Sets to default signal. • U0146:00 — Sets to default signal. • U0151:00 — Sets to default signal. • U0155:00 — Sets to default signal.
Possible cause	• Malfunction in CAN bus communication line • Malfunction in CAN line between PCM and start stop unit • Malfunction in CAN line between TCM and start stop unit • Malfunction in CAN line between ABS HU/CM or DSC HU/CM and start stop unit • Malfunction in CAN line between EPS control module and start stop unit • Malfunction in CAN line between BCM and start stop unit • Malfunction in CAN line between SAS control module and start stop unit • Malfunction in CAN line between instrument cluster and start stop unit
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)]) (See FOREWORD [SKYACTIV-D 1.5])