## DTC U0001:88/U0100:00/U0121:00/U0131:00/U0140:00/U0155:00/U0214:00 [FORWARD SENSING CAMERA (FSC)]

id0902p9029900

| | |
|---|---|
| **Description** | • U0001:88<br>— Module communication error (HS-CAN)<br>• U0100:00<br>— Communication error with PCM<br>• U0121:00<br>— Communication error with DSC HU/CM<br>• U0131:00<br>— Communication error with EPS control module<br>• U0140:00<br>— Communication error with BCM<br>• U0155:00<br>— Communication error with instrument cluster<br>• U0214:00<br>— Communication error with start stop unit |
| **Detection condition** | • U0001:88<br>— Forward sensing camera (FSC) cannot receive the CAN bus communication signal (HS-CAN) for **1 s or more**.<br>— Forward sensing camera (FSC) detects the CAN bus communication line (HS-CAN) malfunction **10 times** continuously.<br>• U0100:00<br>— Forward sensing camera (FSC) cannot receive the CAN signal from the PCM for **1 s or more**.<br>• U0121:00<br>— Forward sensing camera (FSC) cannot receive the CAN signal from the DSC HU/CM for **1 s or more**.<br>• U0131:00<br>— Forward sensing camera (FSC) cannot receive the CAN signal from the EPS control module for **1 s or more**.<br>• U0140:00<br>— Forward sensing camera (FSC) cannot receive the CAN signal from the BCM for **5 s or more**.<br>• U0155:00<br>— Forward sensing camera (FSC) cannot receive the CAN signal from the instrument cluster for **5 s or more**.<br>• U0214:00<br>— Forward sensing camera (FSC) cannot receive the CAN signal from the start stop unit for **1 s or more**. |
| **Fail-safe** | • U0001:88<br>— Inhibits the lane departure warning system (LDWS).<br>— Inhibits the high beam control (HBC) system.<br>• U0100:00<br>— Inhibits the lane departure warning system (LDWS).<br>— Inhibits the high beam control (HBC) system.<br>• U0121:00<br>— Inhibits the lane departure warning system (LDWS).<br>— Inhibits the high beam control (HBC) system.<br>• U0131:00<br>— Inhibits the lane departure warning system (LDWS).<br>• U0140:00<br>— Inhibits the lane departure warning system (LDWS).<br>— Inhibits the high beam control (HBC) system.<br>• U0155:00<br>— Inhibits the lane departure warning system (LDWS).<br>— Inhibits the high beam control (HBC) system.<br>• U0214:00<br>— Inhibits the lane departure warning system (LDWS).<br>— Inhibits the high beam control (HBC) system. |
| **Possible cause** | • Malfunction in CAN bus communication line<br>• Malfunction in CAN line between PCM and forward sensing camera (FSC)<br>• Malfunction in CAN line between DSC HU/CM and forward sensing camera (FSC)<br>• Malfunction in CAN line between EPS control module and forward sensing camera (FSC)<br>• Malfunction in CAN line between BCM and forward sensing camera (FSC)<br>• Malfunction in CAN line between instrument cluster and forward sensing camera (FSC)<br>• Malfunction in CAN line between start stop unit and forward sensing camera (FSC) |

| | |
|---|---|
| **Description** | • U0001:88<br>— Module communication error (HS-CAN)<br>• U0100:00<br>— Communication error with PCM<br>• U0121:00<br>— Communication error with DSC HU/CM<br>• U0131:00<br>— Communication error with EPS control module<br>• U0140:00<br>— Communication error with BCM<br>• U0155:00<br>— Communication error with instrument cluster<br>• U0214:00<br>— Communication error with start stop unit |
| **System wiring diagram** | Not applicable |

**Diagnostic Procedure**

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)].) (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-D 1.5].)