THEFT-DETERRENT SYSTEM [THEFT-DETERRENT SYSTEM]

id0903l1112700

Description	Theft-deterrent siren or theft-deterrent horn sounded
Possible cause	• Wiring harness malfunction • Malfunction in switch which triggers system • BCM malfunction • Customer's mis-operation or misunderstanding
System wiring diagram	Not applicable

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY DTCs** • Perform the DTC inspection for the BCM using the M-MDS. (See DTC INSPECTION [BCM].) • Are any DTCs displayed?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [BCM].)
		No	Go to the next step.
2	**VERIFY OPERATION RECORD** • Has the operation record been stored? (See THEFT-DETERRENT SYSTEM OPERATION RECORD.)	Yes	Go to the next step.
		No	Diagnosis completed (theft-deterrent system does not operate).
3	**VERIFY CONDITION DURING THEFT-DETERRENT SYSTEM OPERATION** • Is the condition during theft-deterrent operation “Alarm” or “Arming”?	Yes	Go to the next step.
		No	Inspect the BCM. If there is any malfunction, replace it. (See BODY CONTROL MODULE (BCM) INSPECTION.)
4	**DETERMINE IF MALFUNCTION CAUSE IS SYSTEM** • Verify what triggered the theft-deterrent system according to the trigger record, and inspect the switch which triggered the system and the related wiring harness. • Is the switch or related wiring harness normal?	Yes	System is normal (explain to the customer that the cause is customer's mis-operation).
		No	Replace the malfunctioning part.