



OPERATION

Machine Torch Operation

Cut Chart - 40 Amp Standard Consumables

- The following recommended settings are for mechanized cutting.
- Torch-to-work distance for the following cut chart is 1/16 inch / 1.5 mm for all cuts.

Shield 120827		Retaining Cap 120600		Nozzle 120826		Electrode 120573		Swirl Ring 120576		PAC123 Torch	
											
Material Thickness		Material		Arc Current (A)	Arc Voltage (VDC)	Recommended Travel Speed		Pierce Delay (Sec.)			
(ga. or in.)	(mm)					(ipm)	(mm/min.)				
26 ga.	0.5	Mild Steel	20	155	250	6850	0				
16 ga.	1.5	Mild Steel	20	155	385	1780	0				
16 ga.	1.5	Mild Steel	40	120	370	10150	0				
1/8"	3	Mild Steel	40	120	140	4950	0.5				
1/4"	6	Mild Steel	40	130	55	1680	1.0				
3/8"	10	Mild Steel	40	140	27	640	†				
1/2"	13	Mild Steel	40	140	19	460	†				
5/8"	16	Mild Steel	40	150	10	250	†				
0.020"	1	Aluminum	20	170	175	4150	0				
0.060"	1.5	Aluminum	20	170	125	3330	0				
16 ga.	1.5	Aluminum	40	130	420	10900	0				
1/8"	3	Aluminum	40	135	140	4450	0.5				
1/4"	6	Aluminum	40	140	53	1620	1.0				
3/8"	10	Aluminum	40	150	25	510	†				
1/2"	13	Aluminum	40	150	17	410	†				
5/8"	16	Aluminum	40	160	8	200	†				
26 ga.	0.5	Stainless Steel	20	160	235	5970	0				
16 ga.	1.5	Stainless Steel	20	160	50	1270	0				
16 ga.	1.5	Stainless Steel	40	130	400	10150	0				
1/8"	3	Stainless Steel	40	140	105	4060	0.5				
1/4"	6	Stainless Steel	40	140	44	1320	1.0				
3/8"	10	Stainless Steel	40	140	21	510	†				
1/2"	13	Stainless Steel	40	150	14	330	†				
5/8"	16	Stainless Steel	40	160	7	180	†				

† To cut material above 6 mm, start torch at edge of material.

† To cut material above 6 mm, start torch at edge of material.