

Equipment Setup

(Upon receiving your Ez-Router/Ez-Plasma/Ez-Plasma XT/Scorpion please inspect the machine before the delivery driver leaves your facility and note any damage to the equipment.)

- The machine will arrive on a pallet. This pallet must be removed before any further installation of the equipment can take place. Also remove all software and hardware boxes that may be secured to the table for shipping.
- Place the machine in a location that will be easily accessible to a forklift or any type of loading/unloading operation. Also keep in mind that the machine will need a minimum of 3' of clearance on all sides!
- After the machine is in the desired location, it should be leveled using leveling pads and if preferred, may be anchored to the floor.
- All machines are delivered using brackets mounted on each axis to insure all axis are secure during transit to the customer's destination. These brackets must be removed before operating the machine!
- If the machine has a table size greater than 5' you may have to install the slave axis transmission assembly. Depending on the chosen form of shipment. If the machine is delivered using a freight truck then the slave axis transmission assembly will be removed so the machine will properly fit in the delivery trailer. If the machine is shipped on a flat bed trailer than the transmission assembly will remain intact to the machine.
- Set up the Control PC. Plug in all cables and hoses accordingly.



- The machine must be plugged into a dedicated and isolated power source. An Isolated Ground Receptacle is preferred for this application.
- The control PC should also be plugged into a dedicated and isolated power source. An Isolated Ground Receptacle is preferred for this application.
- The 25 pin parallel port cable should be plugged into port 1 on the PC (which is the top port on any PC supplied by Ez-Router) and to the port on the side of the control panel of the machine!
- If the machine is equipped with a dust collection system it should be plugged into the receptacle mounted to the side of the control panel. The dust collection system will come equipped with its own power supply whip protruding out of the control panel which will need to be plugged into a 110v power source.
- If the machine is equipped with a vacuum pump it should be plugged into a dedicated power source. The pump will also come with a small 5 pin connector that should be plugged into the opposing 5 pin connector protruding out of the side of the control panel.
- Before operating the machinery all ways and gears should be cleaned and lubricated. Preferred lubrication on all Ez-Routers and Ez-Plasmas is 3-N-1 oil!



- The machine must be plugged into a dedicated and isolated power source. An Isolated Ground Receptacle is preferred for this application.
- The control PC should also be plugged into a dedicated and isolated power source. An Isolated Ground Receptacle is preferred for this application.
- One of the 25 pin parallel port cable should be plugged into port 1 on the PC (which is the top port on any PC supplied by Ez-Router) and the opposing end to the port on the side of the control panel of the machine!
- The other 25 pin parallel port cable should be plugged into port 2 on the PC and the opposing end plugged into the THC (Torch Height Controller)
- The plasma Unit should be plugged into its own power source dedicated and isolated from the machine's power source.
- The plasma unit will come equipped with a 9 pin cable that should be plugged into the THC.
- The plasma unit will also need to be fitted with an air supply that will efficiently keep up with the requested amount of cutting.
- Before operating the machinery all ways and gears should be cleaned and lubricated. Preferred lubrication on all Ez-Routers and Ez-Plasmas is 3-N-1 oil!
- If your machine is equipped with an oxy fuel application, you will have to connect all gas hoses to their corresponding gas bottles. All bottles should be equipped with regulators to insure the preferred gas pressure for the application.



- The machine must be plugged into a dedicated and isolated power source. An Isolated Ground Receptacle is preferred for this application.
- The control PC should also be plugged into a dedicated and isolated power source. An Isolated Ground Receptacle is preferred for this application.
- This machine comes equipped with the Ez-Net Connection. It uses an Ethernet port rather than a parallel port. The Ez-Net should be plugged in to an 110v power supply. It has 2 parallel port connections and an Ethernet connection built into its outer shell. The Ethernet connection will run from the Ez-Net box to the Ethernet port on the control PC. The parallel port labeled “Port 1” will run from the Ez-Net box to the parallel port on the side of the control panel. The parallel port labeled “Port 2” will run from the Ez-Net to the THC. (If your machine is equipped with a High Definition plasma unit, a qualified installation technician will install your equipment.)
- If your machine is equipped with an oxy fuel application, you will have to connect all gas hoses to their corresponding gas bottles. All bottles should be equipped with regulators to insure the required gas pressure for the application.
- The plasma unit will also need to be fitted with an air supply that will efficiently keep up with the requested amount of cutting.
- The plasma Unit should be plugged into its own power source dedicated and isolated from the machine’s power source.
- Proper Grounding is critical to the operating of any High Definition Plasma Unit due to the High Frequency of the Arc Start. This High Frequency produces a large amount of Noise (Radio Frequency Interference). Proper grounding will help deplete this “Noise” before it has an opportunity to get back to the controller. All ground testing and grounding issues should be resolved before installation of equipment to insure optimal machine functionality.

(See documentation on Ground Test Procedures)