

CUSTOMER: SDF PART No. 750-00481-01 PART DESCRIPTION: DF TTV 6160 DOCUMENT NUMBER: OI 588

Deutz Fahr TTV 6160 750-00481-01 Assembly Instructions

1. Scope

The scope of this procedure is to ensure all DF TTV 6160s are assembled and packaged correctly.

2. Purpose

The purpose of this procedure is to outline the steps necessary in the assembly and packing of DF TTV 6160s.

3. Responsibility

It is the responsibility of the operators to ensure the safety of themselves and others, and quality procedures for the product are followed. It is the responsibility of the Team Leader to ensure these instructions are followed.

4. Corrective action:

If a defect or mistake is found, the Team Leader and/or Quality Engineer should be informed immediately. Operators cannot in isolation, decide how an error is to be rectified.

5. Training

All relevant operators should be trained against this OI. Each operator must sign a T9 – staff training record at point of training.



IMPORTANT: Please be aware that the failure to follow these Operator Instructions can lead to a workplace investigation which may result in the company disciplinary procedure been invoked up to and including dismissal. This is in line with company disciplinary procedures.

Please adhere to COVID 19 prevention measures by practising adequate social distancing whilst carrying out this process, wipe down shared tools and equipment before and after use and ensure good hand hygiene and cough/sneeze etiquette where appropriate.

"It is recommended that daily briefing documents such as SSWP's, SPA's, Daily Safe Starts, Task Briefings or equivalent should be updated to reference COVID-19 and specifically social distancing and hand hygiene."

Ref: Sect. 2, CIF SOP for Covid 19;

REVISION:	Α				AUTHOR:	Robert Lowe	SHEET No.
ISSUE DATE:	21/07/21				CHECKED BY:	Mick Lynch	1 of 9
CHANGE No.:	N/A				APPROVED BY:	Conor Lynch	



CUSTOMER: SDF PART No. 750-00481-01 PART DESCRIPTION: DF TTV 6160 DOCUMENT NUMBER: OI 588

Do NOT attempt to carry out this procedure without prior training

Ensure correct PPE is worn at all times.

Ensure hoist and lifting gear is in good working order.

Operators must be trained on:


- SSWP13 Safe System of Work for Hoist operation procedure
- SSWP28 Safe System of Work for Phase 2 Final Assembly & Packing area



Station 1



1.) Place the board onto the assembly line, ensuring a clear work area.



2.) Using the hooked hoist, pick the base off the line.

REVISION:	Α				AUTHOR:	Robert Lowe	SHEET No.
ISSUE DATE:	21/07/21				CHECKED BY:	Mick Lynch	2 of 9
CHANGE No.:	N/A				APPROVED BY:	Conor Lynch	



CUSTOMER: SDF PART No. 750-00481-01 PART DESCRIPTION: DF TTV 6160 DOCUMENT NUMBER: OI 588

3.) Secure the black wear pads to the bottom of the base, add the yellow wear pads with the shorter pads closer to the hitch.











4.) Fasten locknuts to the wear pads with the air gun. Apply white dot to base.



5.) Turn the base onto its flat edge. Retrieve and place the cassette on the board.







6.) Retrieve cylinder, rotate the arm through 90°. Check the threads on the cylinder.

REVISION:	А				AUTHOR:	Robert Lowe	SHEET No.
ISSUE DATE:	21/07/21				CHECKED BY:	Mick Lynch	3 of 9
CHANGE No.:	N/A				APPROVED BY:	Conor Lynch	




CUSTOMER: SDF PART No. 750-00481-01 PART DESCRIPTION: DF TTV 6160 DOCUMENT NUMBER: OI 588



7.) Insert cylinder into cassette, with pipes on bottom. Secure with pin and circlip.



8.) Turn the cassette to it's flat, using the cassette carrier insert cassette into the base.










9.) Position frame above base, lining up the pin holes.





10.) Slide hinge pin through frame, base and cylinder.

REVISION:	Α				AUTHOR:	Robert Lowe	SHEET No.
ISSUE DATE:	21/07/21				CHECKED BY:	Mick Lynch	4 of 9
CHANGE No.:	N/A				APPROVED BY:	Conor Lynch	



CUSTOMER:	SDI	F	PART No.	750-00481-01	PART	DESCRIPTION:	DF	TTV 6160	DOCUMEN	NT NUMBER:	C)I 588
CUSTOMER:		12.) Apply hook, place hook and circlip. Place) Apply war me, place w der frame. F	rning sticker to wooden wedge Fix spring to with white dot.	PART	13.) Inse Apply w shows t	ert nut in thite dot he nut is		m. is arm body, the rods			DI 588
REVISION:	А							AU	THOR:	Robert Lo	owe	SHEET No.
ISSUE DATE:	21/0//21							СН	ECKED BY:	Mick Lyn	nch	5 of 9
CHANGE No.:	N/A							AP	PROVED BY:	Conor Lyı	nch	

750-00481-01

PART No.



OI 588

15.) Line up hole in bracket with hole in tab on drawbar pocket.

SDF

CUSTOMER:


white dot.



Secure with ring pin. Mark with

16.) Attach bolt kit to drawbar pocket with cable tie, mark with white dot when done.






17.) Position the spring on the frame, place a washer beneath the spring and secure with an additional washer, nut and bolt.

PART DESCRIPTION:

DF TTV 6160



18.) Position latching blocks in place, slide pin through frame and latching blocks.





DOCUMENT NUMBER:







		_	_	•				
REVISION:	А					AUTHOR:	Robert Lowe	SHEET No.
ISSUE DATE:	21/07/21					CHECKED BY:	Mick Lynch	6 of 9
CHANGE No.:	N/A					APPROVED BY:	Conor Lynch	



CUSTOMER: SDF PART No. 750-00481-01 PART DESCRIPTION: DF TTV 6160 DOCUMENT NUMBER:

19.) Secure pin with a roll pin. Mark with white dot when done. Tighten nut and bolt, mark with white dot when done.









20.) Using the slide hammer, secure hinge pin with bevelled washer and circlip. Mark with white dot.





21.) Slide latching hook through frame, secure hooks with inner and outer roll pins. Attach cable bracket with nut and bolt. Mark with white dots when done.









OI 588









22.) Attach stickers to frame. Cable tie latching hook to base, mark with white dot.

				!				
REVISION:	А					AUTHOR:	Robert Lowe	SHEET No.
ISSUE DATE:	21/07/21					CHECKED BY:	Mick Lynch	7 of 9
CHANGE No.:	N/A					APPROVED BY:	Conor Lynch	

750-00481-01

PART No.



OI 588

23.) Secure bolt kit to frame with cable tie. Mark with

white dot.

CUSTOMER:

SDF





PART DESCRIPTION:

25.) Place lift links into plastic sleeve, fold in both ends, secure with cable tie. Place accessories into plastic bags.

DF TTV 6160



DOCUMENT NUMBER:





24.) Retrieve drawbar from box, place pin through hole, apply sticker

Station 3

and cover in foam wrap.





26.) Place blue plastic liner into crate, using hoist, lower assembly into box.







REVISION:	Α				AUTHOR:	Robert Lowe	SHEET No.
ISSUE DATE:	21/07/21				CHECKED BY:	Mick Lynch	8 of 9
CHANGE No.:	N/A				APPROVED BY:	Conor Lynch	



750-00481-01 **DF TTV 6160 SDF OI 588** CUSTOMER: PART No. PART DESCRIPTION: DOCUMENT NUMBER: 29.) Fill out Box number & 27.) Pack the drawbar first, then stock log, staple address lift links, add all accessories. A and packing list to box. drawing should be included. 28.) Close plastic liner, secure with cable tie. Place lid on box, press in corners with corner tool, hammer down latches. REVISION: Α SHEET No. AUTHOR: **Robert Lowe** ISSUE DATE: 21/07/21 CHECKED BY: Mick Lynch 9 of 9 CHANGE No.: APPROVED BY: N/A Conor Lynch