DRIVING BOXES

DRIVING BOXES

The shoe and wedge face of new driving boxes to be accurately laid off and boxes machined in quantities or sets when possible The shoe and wedge faces of driving boxes (steel or bronze) to be straight and parallel machined smooth and free of tool marks.

Cast steel driving boxes without bronze shoe and wedge face when undergoing repairs, to have the shoe and wedge faces checked and if found rough taper or out of parallel should be trued up removing only sufficient material to insure straight and parallel faces.

Cast steel driving boxes having bronze shoe and wedge faces when undergoing repairs to be brought back to standard by rebronzing and machining to size

The best method for securing bronze to shoe and wedge faces of driving boxes is shown by illustration page 18

Hub face of driving boxes to be machined and drilled for securing bronze hub face as shown on drawings of driving boxes.

Bronze hub face should be poured on driving boxes before the crown brass is applied

To remove bronze from hub face or shoe and wedge faces of driving boxes, heat the box to about 600 degrees F and chip the bronze off or cut grooves in the bronze through to the steel base metal, then remove bronze with handle chisel and sledge.

Crown brass fit in driving boxes to be machined smooth and straight. Driving boxes when undergoing repairs (when crown brass is removed) to have crown brass fit checked and if found out of round or taper, to be re machined When re-machining crown brass fit in driving boxes only sufficient metal should be removed to true up the box—the maximum diameter must not exceed 5/16 inch over the original diameter See illustration page 17 C

Driving box spring saddle pockets should be squared

Worn cellar bolt holes should be closed by welding and then re drilled.

All holes leading from oil cavity in top of driving box to crown brass must be plugged.

Driving boxes equipped for Alemite lubrication see Soft Grease Lubrication Folio.

Continued on page 16