## **PGM-CARB Control System**

## Troubleshooting Flowchart ——— Ignition Coil Signal -Self-diagnosis LED indicates code 8: A problem in the ignition coil signal circuit. LED indicates CODE 8. Turn the ignition switch OFF. Remove EFI, ECU fuse in the under-hood relay box for 10 seconds to reset control unit. Start the engine and allow to Intermittent failure. **PRIMARY** Check the connectors NO WINDING Does LED indicate CODE 8? at the ignition coil and **TERMINALS** control unit. YES Turn the ignition switch OFF. Disconnect the primary terminals from the ignition coil. Measure resistance between the SECONDARY B and D terminals. WINDING **TERMINAL** NO Is there approx. 2000 $\Omega$ ? Replace ignition coil. YES Reconnect the primary terminals to the ignition coil. (To page 6-35)



