Contoso Air Service Bulletin SB-HP24S-07

Applies to: HP-24S outdoor units manufactured 2021-01 through 2022-12

Subject: Outdoor fan motor bearing wear

Symptom

A grinding or rasping noise from the outdoor unit that rises and falls with fan speed, often loudest after a defrost cycle. Fault code D07 may also be logged.

Cause

Early bearing wear on the 1/4 HP fan motor. The motor windings are normally unaffected.

Action

1. Isolate power and check the fan shaft for radial play.
2. Play under 0.5 mm: replace the bearings with kit BRG-KIT-1.
3. Play over 0.5 mm or a scored shaft: replace the motor (FAN-HP24).

Warranty

Covered under the standard parts and labor warranty. Quote this bulletin on the claim.