

Product Safety Recall Notice R-2025-014

Product Safety · 2025-02 · Issue 2

1. Scope and affected product

This notice records the field action raised under reference R-2025-014 and sets out the product affected, the population in scope, and the actions required of holders of affected stock.

The action applies to the valve assembly BV-12 only. The assembly is identified on the product label and on the packing documentation by its part number. Holders should confirm the part number before applying any action described in this notice, as adjacent assemblies in the same series are not in scope and have not been assessed under this action.

Field	Entry
Reference	R-2025-014
Raised	2025-02-06
Classification	Field safety action
Product affected	BV-12 valve assembly
Status	Open

The population in scope is defined by build date and by the batch identifiers listed in section 3. Assemblies outside those identifiers are not affected and require no action. Units already returned under separate arrangements are excluded from this action and are tracked separately.

This notice supersedes Issue 1, which was withdrawn following a revision to the batch identifiers in section 3. No other part of the notice was changed.

2. Defect description

The condition arises at the seal interface between the valve body and the housing. Under sustained thermal cycling at the upper end of the declared operating range, the interface may lose sealing contact, permitting seepage past the seal face.

The condition develops progressively. Early indications are a small deposit at the interface and a measurable reduction in retained pressure across a hold test. Complete loss of sealing contact has not been observed in the field and is not expected within the assessed service interval, but the condition is progressive and does not self-correct.

Characteristic	Observation
Location	Seal interface, valve body to housing
Onset	Progressive, under sustained thermal cycling
Indication	Deposit at interface; reduced retained pressure
Detection	Hold test at service interval

Assessment of the condition and of the corrective design activity is recorded under separate engineering references and is not reproduced in this notice. Holders requiring the engineering assessment should request it through the usual channel.

3. Affected batches

The following batch identifiers are in scope. Identifiers are printed on the assembly label and repeated on the packing note.

Batch	Build period	Units in scope
5102	2024-10	340
5118	2024-11	412
5133	2024-12	388
5147	2025-01	295

Batches outside this list are not in scope. Where a batch identifier is illegible, the assembly should be treated as in scope until the build period can be confirmed from the packing documentation.

Units held as uncommitted stock should be quarantined and reported on the return schedule described in section 4. Units in service should be assessed at the next planned maintenance opportunity and reported whether or not the condition is present, as the population figures depend on complete returns.

4. Containment actions

Holders of affected stock are required to quarantine uncommitted units immediately and to report holdings against the reference above.

Action	Applies to	Required by
Quarantine	Uncommitted stock	On receipt of this notice
Report holdings	All holders	14 days from receipt
Assess in service	Units in service	Next planned maintenance
Return affected units	Units confirmed affected	On assessment

Replacement assemblies are available against the same part number from current production. Current production is outside the batch identifiers listed in section 3 and is not affected by this action.

Correspondence relating to this action should quote the reference above. The action remains open until the return position is reconciled and the closure record is raised.