



Ministry
of Defence



Defence Fire and Rescue

Tactics, Techniques & Procedures

Tactics, Techniques & Procedures

Document No: ATTP A51

Title: CAT 08 Upgrade RAF Odiham - 2 MPRVs + 1 Striker

Date Issued: 13 09 2022

Supersedes: N/A

Review Date: 02 02 2024

Stakeholders: DFR HQ ✓ Capita Fire and Rescue ✓
RN Aircraft Handler ✓ RAF Fire and Rescue ✓
DFRS LEC Other FRS Providers
DFRS (Retained) Officers DFRS (USVF)

Technical Approved RAF & CFR ARFF SME
Operations Committee

Sponsor Details: Alex Clark
Capita Fire & Rescue (CFR) Headquarters
Reading Bridge House,
1st Floor,
George Street,
Reading,
RG1 8PJ

Contact: philip.mcguinness@capita.com

Conditions of Release

1. This information is Crown Copyright and the intellectual property rights for this publication belong exclusively to the Ministry of Defence (MOD). No material or information contained in this publication should be reproduced, stored in a retrieval system or transmitted in any form outside MOD establishments except as authorised by both the sponsor and the MOD where appropriate.
2. This information is released by the United Kingdom Government to a recipient Government for defence purposes only. It may be disclosed only within the Defence Department of a recipient Government, except as otherwise authorised by the MOD.
3. This information may be subject to privately owned rights.

TACTICS TECHNIQUES PROCEDURES



Boeing C17 Globemaster (Category 8) RAF Odiham - 8 FFTRs

MPRV (Crash 1)

MPRV (Crash 2) (IC)

Striker HRET (Crash 3)

SUBJECT	PAGE
Crewing for TRA ICAO8 RAF Odiham	3
Vehicle Media Quantities (Specifications)	4
DSA02 ARFF Regs: Table 1 - Minimum useable amounts of extinguishing agents	5
DSA02 ARFF Regs: Table 3 - Individual Aircraft Fire-fighting Media Requirements	6
RAF Odiham ICAO8 Worst-case Credible Scenario (WCS)	7
Time In Attendance: 01.15 Minutes	8
Fire Extinguished: 01:15 – 02:15	9
Time: 02:15 – 04:30	10
Time: 04:30 – 10:00	11
Time: 20:00+ Incident now in LAFS Control	12

Crewing for TRA ICAO8 RAF Odiham

APPLIANCE A - MPRV (Crash 1)

IC (A1)	Cpl
DRIVER (A2)	SA
BA (A3)	SA

APPLIANCE B - MPRV (Crash 2)

OIC (B1)	Sgt
DVR (B2)	SA
Vehicle I/C (B3)	SA

APPLIANCE C - Striker HRET (Crash3)

IC (C1)	Cpl
DVR (C2)	SA

Vehicle Media Quantities

MPRV Firefighting Media Quantities

10. Table 2 below provides the firefighting media quantities and specifications.

Table 2

Water Capacity	4600 Ltrs	Firefighting foam availability	650 Ltrs
Monitor Discharge Rate	3000 Ltrs per Min 1500 (half flow setting)	Ladder	10.5M and 5.5M
Monitor Throw	55 Metres	FAFA (in Cab) CO ₂ Dry Powder	2 kg 6 kg
Type and Quantity of Dry Powder	Monnex 250 kg Discharge Rate 7 kg/s	Vehicle Rider Strength	4/5

Striker HRET Firefighting Media Quantities

Table 2:

Water Capacity (Litres)	9500
Bumper Turret Discharge Rate (Litres per min)	6000 – (3000 at half flow rate)
Piercing Spike (Litres per Min)	946
Hydro Chem Roof Turret	3745/1892
Firefighting Foam Availability	1140
Ladder	10.5m or 5.5m
CO ₂ Carried (Cab)	2kg
Dry Powder Carried (Cab)	6kg
Thermal Imaging Camera - FLIR	Yes
Type & Quantity of Dry Powder	Monnex 175 kg Discharge Rate (7.8 /10 kgs per sec)
Vehicle Ride Strength	2/4

DFSA 02 ARFF Regs: Table 1

Table 1 below shows - Minimum useable amounts of extinguishing agents

ARFF Category	Foam meeting performance level B		Foam meeting performance level C		Complementary agents (Kg)	
	Water (Ltrs)	Discharge Rate Foam Solution (Lpm)	Water (Ltrs)	Discharge Rate Foam Solution (Lpm)	Minimum Dry Powder (Kg)	Discharge Rate (Kg/Sec)
Special	90	60	60	40	18	1.25
1	230	230	160	160	45	2.25
2	670	550	460	360	90	2.25
3	1200	900	820	630	135	2.25
4	2400	1800	1700	1100	135	2.25
5	5400	3000	3900	2200	180	2.25
6	7900	4000	5800	2900	225	2.25
7	12100	5300	8800	3800	225	2.25
8	18200	7200	12800	5100	450	4.5
9	24300	9000	17100	6300	450	4.5
10	32300	11200	22800	7900	450	4.5
H1	500	250	350	175	23	2.25
H2	1000	500	700	350	45	2.25
H3	1600	800	1070	535	90	2.25


Table 3 below shows – Individual Aircraft Fire-fighting Media Requirements

Aircraft Type	Water Calculation (Ltrs)	Aircraft Category	Min Water Required ³ (Ltrs)	Discharge Rate ⁴ (if different) to that provided in Table 1 (Lpm)
Atlas (A400M)	12920	8	18200	
Avenger	1048	3	1200	
BAE 146 CC Mk2 (RJ 70)	5637	5	5637	3221
BAE 146 C Mk 3 (RJ 100)	7631	6	7900	
C130	8647	6	8647	4324
C17	18060	8	18200	

Worst-case Credible Scenario

1	ICAO Category	ICAO-8
Event - what has occurred		
2	Time of Day (Daylight or Darkness)	1300 hrs (daytime)
3	Weather conditions, wind direction and strength	Weather dry, calm wind
4	Event (What has happened)	<p>C17A Globemaster enroute to RAF Odiham from Mali with PAX and Chinook Cargo. 10 PAX / 5 Crew.</p> <p>A heavyweight high-speed landing causes the undercarriage to fail. Tyres burst and brake fires initiate due to brake temperatures more than 1000 degrees Celsius. The aircraft remains intact and comes to rest at CX Map location H9. Brake and landing gear is on fire. External fire breaches aircraft fuselage and emits fire gases into occupied aircraft. 4 x Crew and 6 x PAX self-rescue through cockpit emergency escape and available exits retrospectively. 1 x Crew in cockpit and 4 x PAX in fuselage require rescue due to injuries sustained during heavy landing.</p> <p>ES message from ATC, C17, undercarriage failure Rwy 09, Crash Map location K-7, 15 POB</p>
5	What are the contributing factors	
What are the consequences		
6	What is on Fire and Why	Tyres burst, and brake fires initiate due to brake temps more than 1000 degrees Celsius. The aircraft remains intact and comes to rest at Crash Map Location K-7
7	Extent fire spread	Fire has spread from the wheel brake assembly to fuselage.
8	Time taken to extinguish	Approximately 60 seconds
9	Number of Persons Evacuating, and from where and how	1 X Crew and 4 X PAX need rescue.
10	Trapped personnel requiring rescue	1 X Crew and 2 X PAX need rescue.
11	Incident Assumptions	
12	Additional Considerations	The aircraft is unarmed.


TIME IN ATTENDANCE 01:15 Minutes



Comments

- Combine Enter Runway 09 via Charlie and fast track
- Time in attendance 01:15 (As carried out in area response assessment)
- Incident Commander will: -
 - Carry out initial scene assessment and DRA of the incident enroute.
 - Initiate MIP enroute, (this will trigger a response from various station assets to assist when applicable and safe to do so).
 - A call to LAFRS will be made on activation of the MIP either by ATC or using airwaves radio).
- 2 x MPRV (A & B) 1 x Striker (C) in attendance.
- A2, B2 and C2 positions vehicles: MPRV A (Rescue) MPRV B (Nose/Portside) & Striker C (Starboard).


Fire Extinguished 01:15 - 02:15



Comments

- Incident Commander to carry out initial scene assessment and DRA of the incident.
- C1 to operate the bumper monitor (6000 l/pm) for 60 seconds minimum and will continue until HRET is deployed for use of FLIR and safety covering line.
- B2 to operate MPRV B bumper monitor, (3000 l/pm) for 60 seconds minimum. Total discharge rates of Vehicle B+C exceed the 7200 lpm required for C17.
- I/C to consider use of dry chem
- C2 To deploy HRET For use of FLIR and Covering line.
- A2 To carryout initial PEMS and hand over to medics for triage once medics on scene


INITIATE RESCUE: TIME 02:15 – 04:30 Minutes



Comments

- Incident Commander to carry out initial scene assessment and DRA of the incident.
- A2, B3 deploy 3 x lengths of 45mm lay flat hose.
- A1 & A3 Don BA Sets for Rapid deployment
- B2 dismounts MPRV B and rolls out 2 x 45mm hose as a guard branch.
- C1 appointed as 2 IC (Rescue Sector Commander) to assist OIC With spans of control
- C2 to remain on vehicle as covering lines and utilising FLIR
- FFP3 Masks to be donned by All within the risk area


TIME 4:30 - 10:00 Minutes



Comments

- Incident Commander to carry out initial scene assessment and DRA of the incident.
- A1 and A3 deploy under rapid deployment procedures with TIC. Confirm with I/C Internal condition and commence ventilation to improve conditions, assess PAX and remain in position until Medics on A/C
- C1 Continues as 2 IC (Rescue Sector Commander)
- B3 conducts hose management
- A2 Pump ops as MPRV isn't a standalone pump and MPRV has 4550L of water Media for Entry
- B2 stands on guard branch. C2 Covering lines with HRET.
- I/C Briefs B3 and Medics to don FFP3 Mask and enter fuselage to carryout triage of trapped casualties.
- A1 & A3 Exit aircraft and doff sets. BA Discontinued

TIME 20:00+ - Incident now LAFS Control



Comments

- LAFS Make staggered attendance, consider STOP message for further appliance attending if incident under control
- Appoint complete ICS, Safety officer
- VAHS to assess aircraft
- Police to scene for evidence preservation
- Environmental officer
- Media officer
- Ensure adequate resources for the safe resolution of the incident
- Engineers
- AAIB