## DIAGNOSTIC TROUBLE CODE CHART

DIB0L-01

	<u> </u>	·
DTC[[No. (SEE[[PAGE)	Circuit Inspection	Trouble Area
B2780 (DI-894)	Key unlock warning switch malfunction	Key unlock warning switch Wire harness
B2784 (DI-897)	Transponder key coil malfunction	Transponder key amplifier with coil
B2793 (DI-898)	Transponder chip malfunction	Кеу
B2794 (DI-899)	Unmatched encryption code	Key Transponder key amplifier
B2795 (DI-900)	Unmatched key code	Key Unregistered key inserted before
B2796 (DI-901)	No communication in immobiliser system	Key Transponder key amplifier with coil Wire harness Transponder key ECU
B2797 (DI-903)	Communication malfunction No.1	Key Wire harness Transponder key amplifier with coil Transponder key ECU
B2798 (DI-906)	Communication malfunction No.2	Key Transponder key amplifier with coil Wire harness Transponder key ECU
B2799/99 (DI-906)	Engine immobiliser system malfunction	Wire harness Transponder key ECU ECM

## HINT:

To reduce the unnecessary exchange of Transponder key ECU, check that a trouble occurs with the original Transponder key ECU at the time of exchanging Transponder key ECU and the trouble will disappear with a new Transponder key ECU.