

Mechanical seal failure and product release (P-3401)

Incident Report | Tier 1

1. Asset

Field	Value
Asset tag	P-3401
Name	Ester feed pump A
Class	CP200
Plant / Unit / Area	MT / U300 / Esterification
Service duty	Hot organics transfer - molten ester feed, 185 C
Criticality	A
Installed on	2019-05-14

2. Findings

P-3401 mechanical seal failed with product weeping at the gland and dripping on the outboard side (WO-2024-0117), 14 h downtime. Cartridge seal replaced. Seal faces showed thermal distress consistent with inadequate flush. The flush-plan deviation flagged in 2021 remains open; correcting the seal flush plan to OEM spec is the standing recommendation.

3. Recommendation

Verify the seal flush plan on this and the sister CP200 pumps against the OEM MSC-CP200 manual (API Plan 11) and correct any field deviation before further seal replacement.