

Mechanical seal failure, faces scored (P-3105)

Incident Report | Tier 1

1. Asset

Field	Value
Asset tag	P-3105
Name	Solvent bottoms pump
Class	CP200
Plant / Unit / Area	MV / U100 / Distillation
Service duty	Hot organics transfer - column bottoms, 190 C
Criticality	A
Installed on	2020-02-20

2. Findings

P-3105 mechanical seal failed with leakage at the gland follower and product on the baseplate; seal faces found scored (WO-2025-0289), 16 h downtime. Same failure signature as P-3401 in 2024. Flush plan again suspected off-spec. Third seal-flush concern across the sister set.

3. Recommendation

Verify the seal flush plan on this and the sister CP200 pumps against the OEM MSC-CP200 manual (API Plan 11) and correct any field deviation before further seal replacement.