

Mechanical seal failure, flush plan confirmed off-spec (P-3402)

Incident Report | Tier 1

1. Asset

Field	Value
Asset tag	P-3402
Name	Ester feed pump B
Class	CP200
Plant / Unit / Area	MT / U300 / Product Transfer
Service duty	Hot organics transfer - ester product, 175 C
Criticality	A
Installed on	2019-05-14

2. Findings

P-3402 mechanical seal failed (WO-2026-0034), 11 h downtime. On strip-down the seal flush was confirmed running Plan Y, NOT the OEM-specified Plan 11. This is the third mechanical-seal failure across the CP200 sisters in 22 months (P-3401 2024, P-3105 2025, P-3402 2026), cumulative 41 h downtime. Root cause tied to the long-standing flush-plan deviation. Action: bring all four CP200 seal flush plans to OEM Plan 11 per the MSC-CP200 manual.

3. Recommendation

Verify the seal flush plan on this and the sister CP200 pumps against the OEM MSC-CP200 manual (API Plan 11) and correct any field deviation before further seal replacement.