

Seal flush line inspection after blockage (P-3401)

Inspection Report | Tier 1

1. Asset

Field	Value
Asset tag	P-3401
Name	Ester feed pump A
Class	CP200
Plant / Unit / Area	MT / U300 / Esterification
Service duty	Hot organics transfer - molten ester feed, 185 C
Criticality	A
Installed on	2019-05-14

2. Findings

Following WO-2021-0453 the API Plan 11 flush line on P-3401 was found partially choked at the orifice. Line and strainer cleaned. The flush arrangement in service could not be confirmed against the OEM-specified Plan 11; recommend verifying the seal flush plan against the Rheinwerk MSC-CP200 manual and standardising across all four sister pumps.

3. Recommendation

Verify the seal flush plan on this and the sister CP200 pumps against the OEM MSC-CP200 manual (API Plan 11) and correct any field deviation before further seal replacement.