

Risk Assessment No: WP-010				Task: Motor Control Centre and Electrical Isolation						
Prepared By: Derick Bibby				Date: 02.08.2026			RA Review Date: 01.08.2027			
				Reviewed By: Lee Hardy			Date: 02.08.2026			
PPE: Safety Footwear, High Visibility Jacket, High Visibility Trousers, Hard Hat, Gloves, Ear Defenders, Mask, Eye Protection, FFP3 dust mask. Arc-flash rated overalls, insulated gloves and boots for LV work, voltage-rated tools.										
Hazard	Persons at Risk	L	S	R	Control Measures	L	S	R		
Arc flash / arc blast at MCC panel	Electricians	2	5	10	- Only authorised competent electricians may open live panels — under electrical permit. - Arc-flash rated PPE per site electrical risk assessment. - Voltage-rated insulated gloves and tools; face shield and hood as risk-assessed. - Live-work minimised — de-energise wherever practicable. - Boundary and warning signage placed before panel access.	1	5	5		
Electric shock — MCC, motor terminal boxes, damaged cables	Operator Maintenance Electricians	3	5	15	- Only competent authorised electrical persons open MCC panels or motor terminal boxes. - Electrical work under signed permit-to-work with LOTO and voltage test. - Fixed installation inspection to BS 7671 on documented periodic cycle. - RCD protection tested monthly; results recorded. - Cable routes protected against mechanical damage.	1	5	5		
Failure of isolation — incomplete LOTO leading to re-energisation	Maintenance Contractors	3	5	15	- Every energy source (electrical, hydraulic, pneumatic, water, gravitational, stored) individually locked with the operator’s personal padlock and tagged. - Zero-energy proved by attempted start and gauge/meter verification. - Only the lock-owner may remove their lock — Lock Removal Procedure signed by SHEQ Manager if unavailable. - LOTO station stocked and audited monthly.	1	5	5		
Electrical fire at MCC or motor terminal box	All personnel	2	5	10	- CO₂ extinguisher at MCC entrance; annual service and monthly visual check. - Fixed installation and thermographic surveys on documented cycle. - Cable routes free of combustibles; MCC ventilation clean. - RCD protection tested monthly.	1	5	5		
Slips, trips and falls on the same level	All plant personnel	4	3	12	- Anti-slip walkways and stair-treads; wash-down at end of shift. - No trailing hoses or cables across walkways — stored on reels or coiled. - Immediate clean-up of oil, hydraulic fluid or fines spillage. - Adequate task lighting throughout the plant.	2	3	6		

Stored energy — hydraulic accumulators, pneumatic receivers	Maintenance Contractors	3	5	15	• Correct footwear with slip-resistant sole to SRC. • Bleed hydraulic accumulators to zero pressure and confirm via gauge before opening manifolds. • Drain air receivers to zero via test valve before hose or fitting removal. • Padlock the isolator on the pump or compressor supplying the circuit. • PSSR examination of accumulators and receivers at statutory interval.	1	5	5