STANDARD OPERATING PROCEDURE

Equipment Calibration

Document no.	SOP-104	**Revision**	3
Effective date	June 12, 2026	**Owner**	Quality Manager
Applies to	All lab shifts	**Review cycle**	Annual

1. Purpose

This procedure describes how to calibrate bench equipment at the start of each shift so that test results are accurate and calibration records are complete.

2. Scope

Applies to all bench scales and meters in the testing lab. Does not cover annual calibration performed by the external vendor.

3. Before you begin

- Calibration weight set (Class F1), stored in the cabinet by the door
- Calibration log for the current month
- Lint-free cloth

4. Procedure

1. **Power on the unit and let it warm up for 15 minutes.**
   - Confirm the display shows the self-test pass message.
   - If the self-test fails, stop and tag the unit.

2. **Record the ambient temperature in the calibration log.**
   - The room must be between 18 °C and 25 °C.

> **CAUTION**
> Do not adjust the calibration dial while a test is running. Doing so invalidates the results of the current batch.

3. **Run the zero check and note the reading.**
   - Remove everything from the pan and close the draft shield.
   - Press ZERO and wait for the stable indicator.

4. **Place the 100 g reference weight on the center of the pan.**
   - The reading must be within ±0.002 g of 100.000 g.

5. **If the reading is out of tolerance, run the internal calibration routine and repeat step 4.**

6. **Sign and date the calibration log.**
   - Your supervisor initials the log at the end of the shift.

5. Records

Date	Unit ID	Reading (g)	Pass / Fail	Initials