Dental Laboratory Bench and Service Survey

Visit Details

Claim: CLM-26-348735. Property: Birchstone Dental Lab LLC, 1624 Alder Court, Suite D.

Inspection completed 2026-08-30 by Elliot Chen.

The laboratory has long fabrication benches served by a central wash-up island. Water escaped inside that island and spread beneath the bench plinths toward the polishing area. The survey took place after technicians moved portable tools to a dry finishing bench at the opposite end of the room.

Prior Conditions

The laboratory's tool inventory photographs show straight plinths before the event. Behind the lifted island panel, fasteners are bright above the current wet line. No historic tide mark was seen at the finishing-bench comparison opening.

Interior Scope

Lower wall linings behind the fabrication benches are softened where the water collected. Vinyl planks at the polishing approach have lifted end joints. Ceiling service infill near the island carries splash staining from the open riser. The dry finishing bench area has flat joints and was left as the comparison area.

Millwork Scope

Several bench plinths have swollen and one island base panel has split around a screw. The bench tops and drawer faces are flat. New substrate panels can be fitted below the retained working surfaces, with the tool rails kept in their existing positions.

Demolition Scope

The removal sequence starts with bench plinths so the wall bases can be reached. Loose floor planks lift toward the polishing approach. Wallboard cutting stops at the last wet stud bay behind the fabrication run. The finishing bench remains protected in place.

Electrical Scope

Low socket strips behind the fabrication plinths show water tracks. The engineer disconnected their feed before the plinths were lifted. The raised outlets at the dry finishing bench remained outside the wet route and passed the comparison test. Restoration includes the wet socket positions and exposed affected branch sections.

Microbial Observations

Freshly opened bench backs have wet paper but no visible colonies. The survey did not remove the fixed upper tool rails or sample concealed material above them.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along wash-up island and fabrication bench. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Dental Laboratory Bench and Service Survey

Trade Coordination

The bench installer and electrician share the narrow plinth route. Floor reinstatement must precede refitting of the low panels, while the working surfaces stay supported. The polishing area can close in half-day blocks; the dry finishing bench remains active.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Wash-up island	Connector bay and base panel	split panel around fixing	Waste trap intact
1B - Wash-up island	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-30; sample point 1
1C - Wash-up island	Lower substrate spot reading	79 on relative 0-100 scale	Accessible surface beside connector bay and base panel
1D - Wash-up island	Retained comparison point	10 on same instrument scale	Waste trap intact
2A - Fabrication bench	Plinths and socket strips	swelling and water tracks	Work surfaces retained
2B - Fabrication bench	Inspection method	Electrical inspection after isolation	Field visit 2026-08-30; sample point 2
2C - Fabrication bench	Lower substrate spot reading	58 on relative 0-100 scale	Accessible surface beside plinths and socket strips
2D - Fabrication bench	Retained comparison point	12 on same instrument scale	Work surfaces retained
3A - Polishing approach	Vinyl end joints	lifted joints over wet backing	Removal route follows benches
3B - Polishing approach	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-30; sample point 3
3C - Polishing approach	Lower substrate spot reading	69 on relative 0-100 scale	Accessible surface beside vinyl end joints
3D - Polishing approach	Retained comparison point	14 on same instrument scale	Removal route follows benches

Dental Laboratory Bench and Service Survey

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4A - Finishing bench	Dry comparison opening	flat joints and no tide mark	Portable tools relocated here
4B - Finishing bench	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-30; sample point 4
4C - Finishing bench	Lower substrate spot reading	11 on relative 0-100 scale	Accessible surface beside dry comparison opening
4D - Finishing bench	Retained comparison point	10 on same instrument scale	Portable tools relocated here

Inspection Record

Working notes were entered during the 2026-08-30 visit. Room labels in the table follow the site route used by Elliot Chen; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.