Surgical Center Restoration Survey

Visit Details

Claim: CLM-26-366148. Property: Lakeshore Surgical Center LLC, 1573 Alder Court, Suite F.

Inspection completed 2026-08-27 by Owen Patel.

The surgical center occupies a long single-floor unit with a central clean corridor and side preparation rooms. The water path ran through the ceiling service spine before reaching the corridor floor. Rooms were vacant during inspection, allowing comparison openings on both sides of the central route.

Prior Conditions

The exposed service-spine supports are clean above the fresh wet boundary. Inspection holes in the perimeter offices show dry cores. The center's previous facilities report records functioning corridor finishes with no open water-damage work order.

Interior Scope

Several preparation-room partition bases and the continuous corridor floor finish are saturated. Ceiling infill and grid sections beneath the service spine show deformation over a long run. Replacement finishes must match the existing cleanable surfaces and joint profiles. Dry perimeter offices were inspected as comparison areas and are outside the marked footprint.

Millwork Scope

Preparation-room cabinet plinths have swollen at their wall returns. Some removable stainless fronts can be detached and reset, while underlying wet substrates require replacement. Storage in the dry perimeter offices remains fixed and is not included on the removal drawing.

Demolition Scope

The removal drawing follows the corridor spine, affected ceiling bays and preparation-room returns. Cleanable finish joints have to terminate at the existing modular breaks. Waste leaves through the service loading door after temporary protection is installed at the clean corridor intersection.

Electrical Scope

Multiple wet branch junctions run beside the service spine. The electrical survey identifies the affected route from the first wet box to the final dry test point. Wet devices and contaminated cable lengths are included in restoration. Separate feeds to the dry perimeter offices remain tagged as retained.

Microbial Observations

The visible wet openings have no colonies at the survey date. The facilities team had ventilated the vacant rooms following extraction. No separate remediation scope was supplied to the surveyor.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along clean corridor and preparation rooms. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Surgical Center Restoration Survey

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Clean corridor	Service-spine ceiling	deformed grid and wet infill	Continuous marked run
1B - Clean corridor	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-27; sample point 1
1C - Clean corridor	Lower substrate spot reading	58 on relative 0-100 scale	Accessible surface beside service-spine ceiling
1D - Clean corridor	Retained comparison point	13 on same instrument scale	Continuous marked run
2A - Preparation rooms	Partition bases	saturated cleanable assemblies	Modular breaks retained
2B - Preparation rooms	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-27; sample point 2
2C - Preparation rooms	Lower substrate spot reading	69 on relative 0-100 scale	Accessible surface beside partition bases
2D - Preparation rooms	Retained comparison point	9 on same instrument scale	Modular breaks retained
3A - Service loading route	Protected corridor intersection	dry passage used for removal	Temporary protection specified
3B - Service loading route	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-27; sample point 3
3C - Service loading route	Lower substrate spot reading	12 on relative 0-100 scale	Accessible surface beside protected corridor intersection
3D - Service loading route	Retained comparison point	11 on same instrument scale	Temporary protection specified
4A - Perimeter offices	Control openings	dry wall cores and intact floors	Separate feeds retained
4B - Perimeter offices	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-27; sample point 4

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4C - Perimeter offices	Lower substrate spot reading	13 on relative 0-100 scale	Accessible surface beside control openings
4D - Perimeter offices	Retained comparison point	13 on same instrument scale	Separate feeds retained

Inspection Record

Working notes were entered during the 2026-08-27 visit. Room labels in the table follow the site route used by Owen Patel; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.