Family Practice Service-Area Inspection

Visit Details

Claim: CLM-26-475747. Property: Redstone Family Dentistry LLC, 1641 Alder Court, Suite E.

Inspection completed 2026-08-31 by Naomi Brooks.

The family practice has a compact service area behind reception, with a narrow return passage to the treatment rooms. A water trail followed the passage base and entered the low equipment recess. Reception staff had covered the dry public floor before the survey team entered.

Interior Scope

Paint has blistered on the service-area wall bases and the passage flooring has detached along one edge. Ceiling infill above the tee is stained. The protected public reception floor remains bonded and was checked at its transition to the passage. The marked work boundary turns into the equipment recess rather than continuing through reception.

Microbial Observations

No visible colonies were recorded in the service cupboard or equipment recess. The dry reception comparison opening was resealed after inspection.

Prior Conditions

Newly exposed studs beside the replaced tee are clean and firm above the wet line. The practice's weekly cleaning checklist has no earlier wet-floor entry in the return passage. No older repair strip was found beneath the detached floor edge.

Electrical Scope

Water reached the low equipment-recess outlets and the passage switch return. These positions were isolated and marked for replacement. The public reception feed remains dry at the comparison opening and is retained.

Millwork Scope

The service cupboard plinth and recess side panel have swollen lower edges. Door leaves and the small counter remain flat. The carpenter can reinstate new lower panels to the existing fronts after flooring and wall closure.

Demolition Scope

Cut out softened lower wallboard along the service return and lift the detached floor edge to the marked dry break. Remove the stained ceiling infill beside the tee. Access and waste handling use the rear staff door, with a protected crossing at the reception transition.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along service area and return passage. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Trade Coordination

The rear staff door provides a short waste route but is also the staff entry. Electrical testing precedes wall closure. The floor and cupboard trades require coordinated short visits so the narrow passage is not blocked by stored materials.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Service area	Wall bases and tee bay	blistered paint and wet core	Clean studs above water line
1B - Service area	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-31; sample point 1
1C - Service area	Lower substrate spot reading	54 on relative 0-100 scale	Accessible surface beside wall bases and tee bay
1D - Service area	Retained comparison point	11 on same instrument scale	Clean studs above water line
2A - Return passage	Floor edge	detached bond near equipment recess	Dry break at reception transition
2B - Return passage	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-31; sample point 2
2C - Return passage	Lower substrate spot reading	65 on relative 0-100 scale	Accessible surface beside floor edge
2D - Return passage	Retained comparison point	13 on same instrument scale	Dry break at reception transition
3A - Equipment recess	Sockets and side panel	water entry and swollen edge	Existing equipment footprint
3B - Equipment recess	Inspection method	Electrical inspection after isolation	Field visit 2026-08-31; sample point 3
3C - Equipment recess	Lower substrate spot reading	76 on relative 0-100 scale	Accessible surface beside sockets and side panel
3D - Equipment recess	Retained comparison point	9 on same instrument scale	Existing equipment footprint

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4A - Public reception	Protected floor control	firm bond at transition	Dry feed retained
4B - Public reception	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-31; sample point 4
4C - Public reception	Lower substrate spot reading	12 on relative 0-100 scale	Accessible surface beside protected floor control
4D - Public reception	Retained comparison point	11 on same instrument scale	Dry feed retained

Inspection Record

Working notes were entered during the 2026-08-31 visit. Room labels in the table follow the site route used by Naomi Brooks; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.