Storage Unit Environmental Survey

Visit Details

Claim: CLM-26-437673. Property: Meadowcrest Storage LLC, 1488 Alder Court, Suite F.

Inspection completed 2026-08-22 by Owen Patel.

The affected unit is split into north and south storage rooms by a masonry partition with two door openings. Water from the common pipe route entered both rooms. The operator emptied the bottom shelving before the visit, leaving cardboard tide marks and an exposed perimeter suitable for inspection.

Interior Scope

The lower wall linings and the perimeter floor finish are wet on both sides of the partition. North-room wallboard breaks under light pressure behind the shelving. In the south room, the sheet finish has curled where adhesive stayed wet. The upper shelf brackets remain secure and the masonry dividing wall is sound.

Microbial Observations

Separate growth areas lie behind the north shelving and at the south perimeter wall. Their locations follow the fresh wet assemblies opened after this discharge. The environmental contractor established two containment work zones, each with its own equipment and waste-transfer route. The doors between zones were sealed during work.

Prior Conditions

The operator's inventory photographs from the week before the incident show clean exposed wall bases in the central aisle. At the current openings, wet gypsum paper carries patchy dark growth. The exposed masonry faces above the water track are dry.

Electrical Scope

Storage-room lighting remained above the observed water path. Low-level outlets beside the south doorway were isolated because moisture reached their back boxes. The engineer marked only those outlet positions; the upper lighting fittings remain on the retained plan.

Millwork Scope

The storage unit has no fitted treatment cabinets. The timber doorway liners have swollen at their feet, and low shelf kickboards have softened against the wet walls. These finish items sit within the general repair scope. Steel shelving is retained after cleaning.

Demolition Scope

Removal starts behind the north shelving and continues around the south perimeter to the marked dry break. Bagging and sealed transfer routes are shown separately for the two rooms. The masonry partition and the high-level shelving brackets remain. The floor coating under the central pallet stands is firmly bonded.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Storage Unit Environmental Survey

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - North storage	Wall paper behind shelving	patchy dark growth on wet backing	Contained work zone north
1B - North storage	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-22; sample point 1
1C - North storage	Lower substrate spot reading	55 on relative 0-100 scale	Accessible surface beside wall paper behind shelving
1D - North storage	Retained comparison point	14 on same instrument scale	Contained work zone north
2A - South storage	Lower perimeter lining	wet core and visible surface growth	Contained work zone south
2B - South storage	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-22; sample point 2
2C - South storage	Lower substrate spot reading	66 on relative 0-100 scale	Accessible surface beside lower perimeter lining
2D - South storage	Retained comparison point	10 on same instrument scale	Contained work zone south
3A - Central aisle	Floor under pallet stands	firm bonded control area	Retained coating
3B - Central aisle	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-22; sample point 3
3C - Central aisle	Lower substrate spot reading	12 on relative 0-100 scale	Accessible surface beside floor under pallet stands
3D - Central aisle	Retained comparison point	12 on same instrument scale	Retained coating
4A - Dividing wall	Exposed masonry above track	dry face and secure brackets	Shelving brackets retained
4B - Dividing wall	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-22; sample point 4
4C - Dividing wall	Lower substrate spot reading	13 on relative 0-100 scale	Accessible surface beside exposed masonry above track
4D - Dividing wall	Retained comparison point	14 on same instrument scale	Shelving brackets retained

Storage Unit Environmental Survey

Inspection Record

Working notes were entered during the 2026-08-22 visit. Room labels in the table follow the site route used by Owen Patel; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.