Orthodontic Suite Opening Log

Visit Details

Claim: CLM-26-678338. Property: Westfield Orthodontics LLC, 1590 Alder Court, Suite B.

Inspection completed 2026-08-28 by Harlan Rowe.

The suite uses small treatment alcoves around a common equipment store. Water ran beneath the store door and along the inner alcove wall. The contractor left several finish samples with reception; the surveyor recorded which samples matched the installed wall and floor assemblies.

Interior Scope

Alcove wall bases are soft on the store side, with dry cores at the outer-wall comparison holes. Vinyl floor seams have opened along the inner corridor. Ceiling tiles beside the store access grille carry splash marks. The sample marked V-2 matches the original floor backing; the other loose samples have no location marking.

Microbial Observations

No visible colonies appeared in the accessible alcove openings. Fine dust on the dry reception storage stayed powdery. The survey contains no microbiological sampling results.

Prior Conditions

Behind the first opened toe-kick, fixings are clean and the fresh wet boundary is sharp. The store's previous stock photograph shows a level bottom shelf and no staining at the inlet. The photograph does not show concealed wall cores.

Electrical Scope

Store-side low sockets contain water tracks beneath their covers. The affected circuit was isolated before probing. The outer alcove outlets remain dry and their faceplates were not removed beyond the control positions. The wet-side replacement scope ends at the dry tested junction.

Millwork Scope

The lowest storage shelf and the alcove toe-kicks have swollen edges. Vertical cupboard doors remain straight. Replacement of the low substrates allows the original fronts to be reset. A dry reception storage run shares the finish color but has no water mark.

Demolition Scope

The opening log identifies the lower strip to remove at each inner alcove return. Floor uplift follows the released seam route. The ceiling scope is confined to stained tiles and the access grille surround. Debris handling uses the equipment-store exit after shelves are emptied.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along equipment store and inner alcoves. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Trade Coordination

Electrical access and wall closure share the inner alcove wall. Shelf reinstatement must wait until the cabinet bases can be refitted over the new floor edge. Patients are being seen in the outer bays while the inner route is released in blocks.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Equipment store	Inlet wall and low shelf	sharp wet line and swollen substrate	Prior stock photo available
1B - Equipment store	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-28; sample point 1
1C - Equipment store	Lower substrate spot reading	65 on relative 0-100 scale	Accessible surface beside inlet wall and low shelf
1D - Equipment store	Retained comparison point	14 on same instrument scale	Prior stock photo available
2A - Inner alcoves	Gypsum at wall bases	soft core at inner returns	Outer comparison holes dry
2B - Inner alcoves	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-28; sample point 2
2C - Inner alcoves	Lower substrate spot reading	76 on relative 0-100 scale	Accessible surface beside gypsum at wall bases
2D - Inner alcoves	Retained comparison point	10 on same instrument scale	Outer comparison holes dry
3A - Alcove corridor	Vinyl seam route	open seams and water under backing	Sample V-2 matches installed floor
3B - Alcove corridor	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-28; sample point 3
3C - Alcove corridor	Lower substrate spot reading	55 on relative 0-100 scale	Accessible surface beside vinyl seam route
3D - Alcove corridor	Retained comparison point	12 on same instrument scale	Sample V-2 matches installed floor

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4A - Reception storage	Cabinet control run	straight dry panels	Matching color alone is not location
4B - Reception storage	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-28; sample point 4
4C - Reception storage	Lower substrate spot reading	14 on relative 0-100 scale	Accessible surface beside cabinet control run
4D - Reception storage	Retained comparison point	14 on same instrument scale	Matching color alone is not location

Inspection Record

Working notes were entered during the 2026-08-28 visit. Room labels in the table follow the site route used by Harlan Rowe; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.