Water Migration Survey

Visit Details

Claim: CLM-26-585247. Property: Fernhollow Dental Group LLC, 1420 Alder Court, Suite B.

Inspection completed 2026-08-18 by Harlan Rowe.

The suite was open for an afternoon walkthrough. Staff had moved treatment carts into the waiting room and left the rear corridor clear. A shallow water track connected the sterilization sink cabinet to the corridor threshold. The examination rooms on the street side remained occupied during the visit.

Prior Conditions

At the opened connector bay, the timber was pale and firm under a probe. Fasteners had no layered rust and there were no older tide lines behind the cabinet. Staff showed a dated cleaning log with no earlier wet-floor entry in this corridor.

Interior Scope

The lower gypsum softened on both faces of the sterilization partition. At the corridor turn, adhesive released beneath the vinyl planks and several end joints rose when walked over. Ceiling panels immediately below the overhead distribution return were stained by splash from the open service chase. The front reception floor remained firmly bonded.

Millwork Scope

The sink cabinet base has split along its rear edge. Two adjoining toe-kick sections are cupped, but the upper doors close squarely and the drawer fronts have no swelling. The damaged lower panels can be replaced while retaining the countertop and unaffected upper storage.

Demolition Scope

The access cuts stop at the first dry stud bay beyond the corridor bend. Lower wallboard, swollen toe-kicks and loose planks cannot be returned to service after removal. The retained upper wall face provides a clean reinstatement edge. Bagged debris can leave through the rear service door without passing through treatment rooms.

Electrical Scope

Three duplex outlets below the sink-side counter contained droplets behind their cover plates. The affected branch was isolated before covers were removed. Conductors at the wet boxes showed surface deposits; boxes on the opposite, dry wall were clean. Replacement devices and a post-work insulation test were included in the electrician's field scope.

Microbial Observations

No surface colonies were seen in the opened cabinet or wall cavity. The observations cover accessible surfaces only; the wall beyond the first dry bay was not opened.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along sterilization and rear corridor. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Water Migration Survey

Trade Coordination

Wall removal must precede device replacement; cabinet reinstatement follows the electrical test. The practice can release the rear corridor for work after 18:00. Flooring cannot bridge the temporary service route until the cabinets are reset, so the trades require separate return visits.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Sterilization	Gypsum at sink return	soft paper and wet core	Rear bay dry above 900 mm
1B - Sterilization	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-18; sample point 1
1C - Sterilization	Lower substrate spot reading	59 on relative 0-100 scale	Accessible surface beside gypsum at sink return
1D - Sterilization	Retained comparison point	10 on same instrument scale	Rear bay dry above 900 mm
2A - Rear corridor	Vinyl plank joints	raised ends and adhesive release	Front threshold firmly bonded
2B - Rear corridor	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-18; sample point 2
2C - Rear corridor	Lower substrate spot reading	70 on relative 0-100 scale	Accessible surface beside vinyl plank joints
2D - Rear corridor	Retained comparison point	12 on same instrument scale	Front threshold firmly bonded
3A - Utility closet	Cabinet plinth	split rear panel	Countertop retained
3B - Utility closet	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-18; sample point 3
3C - Utility closet	Lower substrate spot reading	81 on relative 0-100 scale	Accessible surface beside cabinet plinth
3D - Utility closet	Retained comparison point	14 on same instrument scale	Countertop retained

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4A - Reception	Painted partition	dry control sample	No finish removal marked
4B - Reception	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-18; sample point 4
4C - Reception	Lower substrate spot reading	14 on relative 0-100 scale	Accessible surface beside painted partition
4D - Reception	Retained comparison point	10 on same instrument scale	No finish removal marked

Inspection Record

Working notes were entered during the 2026-08-18 visit. Room labels in the table follow the site route used by Harlan Rowe; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.