Finish Identification and Damage Record

Visit Details

Claim: CLM-26-677883. Property: Greenway Physical Therapy LLC, 1522 Alder Court, Suite C.

Inspection completed 2026-08-24 by Marisol Vega.

The physical-therapy rooms use resilient plank flooring through the exercise area and connecting passage. A loose pre-loss plank from the store cupboard was available for comparison. The owner also showed the surveyor a stone sample being considered for a future reception redesign.

Prior Conditions

Adhesive beneath the retained dry planks is firm. The spare material label predates the water incident and matches the installed backing. There is no older tide line on the exposed cupboard studs or on the removed lower wallboard.

Interior Scope

Water loosened the resilient planks nearest the cupboard and raised joints across the exercise-room entrance. The recovered spare is a commercial vinyl plank with the same backing stamp as the installed material. The stone sample has a different thickness and would need a separate transition detail at the existing dry floor.

Millwork Scope

The cupboard back and two end panels have expanded at their lower edges. Door leaves and the counter surface have no distortion. The plan retains the tall dry cabinet and replaces the affected low panels. Small skirting returns will be refitted after the floor reinstatement.

Demolition Scope

Remove detached planks, soft lower wallboard and the wet ceiling infill over the cupboard service route. The dry floor beyond the exercise-room threshold stays in place. Waste can be taken through the side entrance, keeping the balance equipment in the central room.

Electrical Scope

Four low wall outlets sit within the exercise-room wet perimeter. The electrician found deposits at two opened boxes and moisture at the remaining cable entries. The affected devices are marked for replacement and the branch for retesting. Outlets beyond the dry floor transition are retained.

Microbial Observations

No growth was visible at the fresh access cuts. The wall behind the tall cabinet was inspected through an existing service opening and appeared dry above the wet perimeter.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along exercise entrance and staff cupboard. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Finish Identification and Damage Record

Flooring Specification

The recovered spare is commercial LVT. Its backing stamp matches the installed exercise-room planks. The owner's loose stone sample has a different thickness and came from a separate reception redesign selection.

Trade Coordination

The exercise room can close for two evenings, but the side entrance must remain available to staff. Electrical work precedes wall closure, and the floor installer returns after painting. Cupboard plinths are fitted after the resilient floor has cured.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Exercise entrance	Resilient plank joints	raised joints and released adhesive	Backing matches spare LVT
1B - Exercise entrance	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-24; sample point 1
1C - Exercise entrance	Lower substrate spot reading	69 on relative 0-100 scale	Accessible surface beside resilient plank joints
1D - Exercise entrance	Retained comparison point	10 on same instrument scale	Backing matches spare LVT
2A - Staff cupboard	Back and end panels	expanded lower substrate	Tall dry cabinet retained
2B - Staff cupboard	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-24; sample point 2
2C - Staff cupboard	Lower substrate spot reading	80 on relative 0-100 scale	Accessible surface beside back and end panels
2D - Staff cupboard	Retained comparison point	12 on same instrument scale	Tall dry cabinet retained
3A - Side threshold	Original floor transition	firm dry adhesive	Stone sample is thicker
3B - Side threshold	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-24; sample point 3
3C - Side threshold	Lower substrate spot reading	14 on relative 0-100 scale	Accessible surface beside original floor transition

Finish Identification and Damage Record

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
3D - Side threshold	Retained comparison point	14 on same instrument scale	Stone sample is thicker
4A - Exercise wall	Low outlet boxes	deposits and moist cable entries	Four wet positions tagged
4B - Exercise wall	Inspection method	Electrical inspection after isolation	Field visit 2026-08-24; sample point 4
4C - Exercise wall	Lower substrate spot reading	70 on relative 0-100 scale	Accessible surface beside low outlet boxes
4D - Exercise wall	Retained comparison point	10 on same instrument scale	Four wet positions tagged

Inspection Record

Working notes were entered during the 2026-08-24 visit. Room labels in the table follow the site route used by Marisol Vega; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.