Interior Reinstatement Field Notes

Visit Details

Claim: CLM-26-722023. Property: Pine Ridge Pediatric Dentistry LLC, 1505 Alder Court, Suite B.

Inspection completed 2026-08-23 by Harlan Rowe.

The dental reception slopes gently toward the rear suction plant cupboard. Water collected at that cupboard threshold before entering two treatment bays. Drying hoses had been removed when the surveyor arrived, but equipment impressions and taped cable routes were still visible on the floor.

Interior Scope

The treatment-bay partition feet are wet on the basin side. Flooring edges have lifted along the route to the plant cupboard, while the waiting-room field remains flat. Two ceiling infill panels were marked by water running along the open service channel. The survey sketch uses the carpet transition as the dry stopping point.

Electrical Scope

Moisture was present at the rear-cupboard sockets and at one basin-side junction. Their protective devices were opened and tagged. The waiting-room outlets were tested without finding water entry. New devices are specified at the tagged wet positions, followed by circuit testing after finishes are reinstated.

Demolition Scope

The marked cut line follows the treatment-bay skirting height plus the wet core above it. Loose flooring can be lifted in strips through the rear door. Ceiling removal is limited to the marked infill panels and the connection route. The waiting-room carpet transition is retained.

Millwork Scope

Basin-unit toe-kicks are swollen and the rear cupboard bottom has delaminated. Doors and solid counter surfaces remain square. The repair scope replaces the lower substrate panels and reinstates the original fronts after drying of the surrounding structure.

Prior Conditions

Removed skirting exposed an even fresh wet line and clean fasteners. There was no older paint blistering behind the basin cupboard. A recent chair-servicing sheet records a dry plant cupboard during the maintenance visit.

Microbial Observations

No visible colonies appeared on the removed skirting or at the cupboard backing. Dust deposits on upper shelves were dry. No environmental containment was present at inspection.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along rear plant cupboard and treatment bay one. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Interior Reinstatement Field Notes

Trade Coordination

The cabinet maker needs the electrician's wet-box work completed before the cupboard returns are fitted. Flooring passes beneath removable plinths, requiring a second short cabinet visit. Patient appointments have been moved to the front bays during that sequence.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Rear plant cupboard	Bottom panel and sockets	delamination and water deposits	Dry upper shelf
1B - Rear plant cupboard	Inspection method	Electrical inspection after isolation	Field visit 2026-08-23; sample point 1
1C - Rear plant cupboard	Lower substrate spot reading	62 on relative 0-100 scale	Accessible surface beside bottom panel and sockets
1D - Rear plant cupboard	Retained comparison point	9 on same instrument scale	Dry upper shelf
2A - Treatment bay one	Partition foot	wet core behind skirting	Clean fasteners
2B - Treatment bay one	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-23; sample point 2
2C - Treatment bay one	Lower substrate spot reading	73 on relative 0-100 scale	Accessible surface beside partition foot
2D - Treatment bay one	Retained comparison point	11 on same instrument scale	Clean fasteners
3A - Treatment bay two	Floor edge	lifted edge near hose route	Carpet transition retained
3B - Treatment bay two	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-23; sample point 3
3C - Treatment bay two	Lower substrate spot reading	52 on relative 0-100 scale	Accessible surface beside floor edge
3D - Treatment bay two	Retained comparison point	13 on same instrument scale	Carpet transition retained

Interior Reinstatement Field Notes

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4A - Waiting room	Outlet and floor control	dry socket and flat field	No removal mark
4B - Waiting room	Inspection method	Electrical inspection after isolation	Field visit 2026-08-23; sample point 4
4C - Waiting room	Lower substrate spot reading	14 on relative 0-100 scale	Accessible surface beside outlet and floor control
4D - Waiting room	Retained comparison point	9 on same instrument scale	No removal mark

Inspection Record

Working notes were entered during the 2026-08-23 visit. Room labels in the table follow the site route used by Harlan Rowe; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.