Endodontic Suite Materials Report

Visit Details

Claim: CLM-26-591035. Property: Cypress Point Endoscopy LLC, 1658 Alder Court, Suite F.

Inspection completed 2026-09-01 by Owen Patel.

Water from the instrument-cleaning bay reached the adjacent treatment passage and a small plant compartment. The suite contains a mixture of resilient floor planks and washable wall panels. Staff identified the original material stock numbers from spare pieces kept above the dry records cupboard.

Interior Scope

The cleaning-bay gypsum backing is wet beneath washable finish panels. Resilient floor seams have opened through the adjoining passage. Ceiling tiles beside the service access show water staining. The dry records cupboard area retains firm floor adhesion and intact wall finishes; spare stock from that area matches the installed material numbers.

Electrical Scope

Wet cable entries were found in the plant-compartment sockets and at the cleaning-bay connection box. The electrician disconnected both wet positions before opening covers fully. The records-area comparison socket remained dry. Replacement and test work follows the identified wet branch route.

Demolition Scope

Remove affected washable panels with their softened backing, lifted floor sections and stained ceiling infill. The retained panel grid gives the reinstatement edges. Debris can leave through the side treatment exit after temporary floor protection is laid across the dry records route.

Millwork Scope

The cleaning-unit surround and plant-compartment toe-kicks have expanded at the floor. The upper cupboard fronts are flat and can be kept. New lower substrate pieces will accept the original fronts after the floor is reinstated to the retained grid.

Prior Conditions

The removed hose shows a fresh split; its adjacent tail and cabinet fasteners have no layered corrosion. Exposed backing at the dry records boundary is firm. Stock photographs taken during the last materials count show level passage seams.

Microbial Observations

No colonies were visible at the opened panel edges or behind the toe-kicks. No samples were taken above the closed upper cupboards.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along instrument-cleaning bay and treatment passage. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Endodontic Suite Materials Report

Trade Coordination

Panel removal provides access to the wet connection box, then electrical testing allows backing reinstatement. Flooring fits beneath the removable lower fronts. The treatment exit is available after the final appointment, so the trades have staged access windows.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Instrument-cleaning bay	Washable panels and backing	wet gypsum below retained grid	Spare stock number matched
1B - Instrument-cleaning bay	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-09-01; sample point 1
1C - Instrument-cleaning bay	Lower substrate spot reading	61 on relative 0-100 scale	Accessible surface beside washable panels and backing
1D - Instrument-cleaning bay	Retained comparison point	12 on same instrument scale	Spare stock number matched
2A - Treatment passage	Resilient floor seams	opened seams and wet backing	Level seams in stock photo
2B - Treatment passage	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-09-01; sample point 2
2C - Treatment passage	Lower substrate spot reading	72 on relative 0-100 scale	Accessible surface beside resilient floor seams
2D - Treatment passage	Retained comparison point	14 on same instrument scale	Level seams in stock photo
3A - Plant compartment	Control housings and toe-kicks	water entry and expanded substrate	Matching replacement capacities
3B - Plant compartment	Inspection method	Electrical inspection after isolation	Field visit 2026-09-01; sample point 3

Endodontic Suite Materials Report

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
3C - Plant compartment	Lower substrate spot reading	83 on relative 0-100 scale	Accessible surface beside control housings and toe-kicks
3D - Plant compartment	Retained comparison point	10 on same instrument scale	Matching replacement capacities
4A - Records boundary	Wall and floor controls	firm dry backing and adhesion	Dry route temporarily protected
4B - Records boundary	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-09-01; sample point 4
4C - Records boundary	Lower substrate spot reading	13 on relative 0-100 scale	Accessible surface beside wall and floor controls
4D - Records boundary	Retained comparison point	12 on same instrument scale	Dry route temporarily protected

Inspection Record

Working notes were entered during the 2026-09-01 visit. Room labels in the table follow the site route used by Owen Patel; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.