Ambulatory Care Damage Schedule

Visit Details

Claim: CLM-26-822494. Property: Silverleaf Ambulatory Care LLC, 1607 Alder Court, Suite C.

Inspection completed 2026-08-29 by Marisol Vega.

The ambulatory care unit was inspected between morning and afternoon appointments. A supply run above the dispensary had discharged onto ceiling infill before water reached the preparation-room floor. Staff moved boxed supplies onto raised racks but left the original rack positions marked with tape.

Interior Scope

Dispensary ceiling infill and lower preparation-room wallboard are wet. Flooring below the former rack positions has softened adhesive; the raised rack pads themselves are dry. The marked extent stops at the double-door threshold where the flooring remains bonded. Some water traveled through the ceiling grid before dripping into the second room.

Electrical Scope

The dispensary lighting junction and two low preparation-room outlets were wet at the cover openings. The electrical contractor tagged those positions and isolated the branch. Devices beyond the double doors were checked as dry controls and remain on the retained schedule.

Demolition Scope

Remove deformed ceiling infill, wet wall bases and released floor material within the taped footprint. Retain the dry threshold strip and the fixed raised rack pads. Debris is transferred through the side delivery door while the public corridor remains in use.

Millwork Scope

A dispensary base unit has a swollen bottom and a separated end laminate. The worktop remains level and the upper cupboards are dry. Replacement lower substrates can accept the existing doors after the surrounding finishes are restored.

Prior Conditions

The most recent stocktake photographs show dry ceiling panels above the original rack positions. Opened timber at the current wet edge is firm. No older finish patch was seen under the loosened floor material.

Microbial Observations

No visible growth was observed at the dispensary openings. The dry control strip at the double doors was left intact after probing at its edge.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along dispensary and preparation room. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Ambulatory Care Damage Schedule

Trade Coordination

The dispensary needs ceiling access before electrical testing. Wall closure and base-unit reinstatement follow that test. Floor curing at the preparation-room entrance is scheduled outside patient movement hours, requiring short staggered trade visits.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Dispensary	Ceiling infill and junction	deformed panels and wet junction cover	Temporary cover after plumbing
1B - Dispensary	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-29; sample point 1
1C - Dispensary	Lower substrate spot reading	72 on relative 0-100 scale	Accessible surface beside ceiling infill and junction
1D - Dispensary	Retained comparison point	9 on same instrument scale	Temporary cover after plumbing
2A - Preparation room	Floor at old rack positions	soft adhesive below taped footprint	Raised rack pads dry
2B - Preparation room	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-29; sample point 2
2C - Preparation room	Lower substrate spot reading	83 on relative 0-100 scale	Accessible surface beside floor at old rack positions
2D - Preparation room	Retained comparison point	11 on same instrument scale	Raised rack pads dry
3A - Double doors	Floor control strip	firm bond beyond threshold	Dry stopping point
3B - Double doors	Inspection method	Lifted-edge adhesion comparison	Field visit 2026-08-29; sample point 3
3C - Double doors	Lower substrate spot reading	14 on relative 0-100 scale	Accessible surface beside floor control strip
3D - Double doors	Retained comparison point	13 on same instrument scale	Dry stopping point

Ambulatory Care Damage Schedule

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4A - Dispensary base unit	Bottom and end laminate	swelling and laminate separation	Level worktop retained
4B - Dispensary base unit	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-29; sample point 4
4C - Dispensary base unit	Lower substrate spot reading	73 on relative 0-100 scale	Accessible surface beside bottom and end laminate
4D - Dispensary base unit	Retained comparison point	9 on same instrument scale	Level worktop retained

Inspection Record

Working notes were entered during the 2026-08-29 visit. Room labels in the table follow the site route used by Marisol Vega; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.