

ONMSi v4.10 Alarm List

Generated by	Alarm originating resource type	Alarm type	Specific problem	Additional text	Severity	Cause	Action
OTU	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	ATTENUATION	ATTENUATION	MINOR, MAJOR	The difference between the last and the first marker is over the minor or major threshold	Repair the monitored fiber
	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	ATTENUATION	INJECTION	MINOR, MAJOR	The first marker is over the minor or major threshold	Repair the monitored fiber
	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	ATTENUATION	FIBER_CUT	CRITICAL	The last marker is less tha 3db above the noise floor or the difference between the last and the first marker is over 6dB	Repair the monitored fiber
	LINK	QUALITY_OF_SERVICE_ALARM	FIBER_LENGTH_EXTENSION		MINOR, MAJOR	The length of the fiber is out of the user specified limit.	
	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	NEW_PEAK	NEW_PEAK	MINOR, MAJOR	A new peak has appeared on the trace	
	LINK	QUALITY_OF_SERVICE_ALARM	ORL		MINOR, MAJOR	The Optical return loss is out of the limit	
	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	PEAK	PEAK_RISE	MINOR, MAJOR	The level of a peak has increased more than the threshold limit	Repair the monitored fiber
	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	PEAK	PEAK_ATTENUATION	MINOR, MAJOR	The level of a peak has decreased more the the threshold limit	Repair the monitored fiber
	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	PEAK	MISSING_PEAK	CRITICAL	A referenced peak has disappeared	Repair the monitored fiber
	LINK/SECTION	QUALITY_OF_SERVICE_ALARM	SPLITTER		MAJOR		
	OTU	PROCESSING_ERROR_ALARM	MISSING_OR_CORRUPTED_FILE	(1)	MAJOR	A file of the OTU could not be read properly	Rebuild the OTU (dashboard->Configuration->Rebuild). If this alarm often happens, consult your service center
	OTU	PROCESSING_ERROR_ALARM	LOCAL_MODE	(1)	WARNING	The OTU8000 is controlled by a local PC.	The alarm disappears when the OTU8000 returns to server mode
	OTU	PROCESSING_ERROR_ALARM	INNER_APPLICATION_COMMUNICATION_PROBLEM	(1)	MAJOR	Software problem between processes running on the OTU8000	Rebuild the OTU (dashboard->Configuration->Rebuild). If this alarm often happens, consult your service center
	OTU	EQUIPMENT_ALARM	HARDDISK_SPACE	(1)	MAJOR, CRITICAL	There is a shortage of space on the hardisk that can be caused by a a long interruption of the communication between the server and the OTU8000	Repair the communication problem between the OTU8000 and the server, then tebuild the OTU. If this alarm often happens, consult your service center
	OTU	EQUIPMENT_ALARM	TEMPERATURE	(1)	MAJOR, CRITICAL	The temperature of the OTU8000 is out of the acceptable temperature range.	If this problem persists, consult your service center
	OTU	EQUIPMENT_ALARM	SWITCH_PROBLEM	(1)	MAJOR	The optical switch is not responding	Use web interface to identify which switch is faulty and consult the service center to repair the switch.
	OTU	EQUIPMENT_ALARM	MODULE_PROBLEM	(1)	MAJOR	The OTDR module is not reponding	Consult the service center to repair the OTU
	OTU	EQUIPMENT_ALARM	MODULE_COMPATIBILITY	(1)	MAJOR	The detected OTDR module is different from the registered module and its part number is different.	Change the OTDR module by an OTDR module with the same part number as the initial one. If it is not possible the reference traces must be re-made
	OTU	EQUIPMENT_ALARM	SWITCH_COMPATIBILITY	(1)	MINOR, MAJOR	The detected switch is different from the registered and the number of ports is lower than the initial one.	Replace it with an optical switch with the same capacity or if it not possible remove the links which cannot be monitored anymore
	OTU	EQUIPMENT_ALARM	MISSING_REFERENCE_TRACE	(1)	MAJOR	This alarm can be the result of a corrupted file.	Rebuild the OTU (dashboard->Configuration->Rebuild). If this alarm often happens, consult your service center
OTU	PROCESSING_ERROR_ALARM	TEST_DRIFT	(1)	MAJOR	Incompatibility between two test schedules preventing a test to be excuted according to the programmed schedule	Check with OTU dashboard the tests which are not executed as programmed and Modify the test schedules.	
OTU	EQUIPMENT_ALARM	HARDWARE_PROBLEM	(1)	MAJOR	A serious hardware problem is detected on the OTU8000.	Reboot the OTU (with web interface) and if the alarm happens again consult your service center	
OTU	PROCESSING_ERROR_ALARM	SOFTWARE_PROBLEM	(1)	MAJOR	An unexpected software error has ocured	Reboot the OTU (with web interface) and if the alarm happens again consult your service center	
OTU	EQUIPMENT_ALARM	MEASUREMENT_CYCLE	(1)	CRITICAL	The sequencer is stopped during a predefined period (severity: minor), two predefined periods (severity: major), at the startup (severity :critical).	Check with web interface if OTDR and switch tab dsoes not contain warning. Restart the sequencer from OTU8000 dashboard	
OTU	EQUIPMENT_ALARM	ALARM_OVERFLOW	(1)	MAJOR	The number of alarms kept by The OTU8000 is over the defined limit. It happens when the OTU8000 cannot send the alarm to the server.	Repair the communication problem between the OTU8000 and the server, then tebuild the OTU. If this alarm often happens, consult your service center	
OTU	EQUIPMENT_ALARM	HARDDISK_FAILED	(1)	CRITICAL	Harddisk failure detected on the OTU	Consult your service center	
OTU	EQUIPMENT_ALARM	HARDDISK_BACKUP	(1)	MAJOR	The OTU switched to the backup harddisk due to a problem detected on the main harddisk	Consult your service center	
OTU	EQUIPMENT_ALARM	GENERIC_ALARM	(1)	MAJOR, CRITICAL	This alarm is generated after a failed self diagnostic. Additional text contains the cause of the failure.	Fix the cause of failure if it is related to your network otherwise consult your service center.	
OTU	EQUIPMENT_ALARM	POWER_FAILURE	(1) plugidentifier	MAJOR	Power was cut on a plug that had power at OTU startup. The additional text contains a plug identifier: POWER_FRONT_LEFT, POWER_FRONT_RIGHT, POWER_REAR_LEFT, POWER_REAR_RIGHT	Restore power on the plug	
OTU	EQUIPMENT_ALARM	REBUILD_CLEAR	(1)	CRITICAL	After the OTU has identified that the tests and links configuration were co	Rebuild the OTU (dashboard->Configuration->Rebuild)	
Server	OTU	COMMUNICATIONS_ALARM	HEARTBEAT	(1)	MAJOR	The server has not received information from the OTU8000 for more than	Check the communication between the server and the OTU8000
	OTU	COMMUNICATIONS_ALARM	MISSING_AUTOTEST	(1)	MAJOR	The server has not received information from the self diagnostic of the OTU	Check the communication between the server and the OTU8000
	OTU	PROCESSING_ERROR_ALARM	AUTOTEST_LINK_SYNCHRONIZATION	(1)	MAJOR	Link configured in database and in the OTU are not the same	Rebuild the OTU (dashboard->Configuration->Rebuild). If this alarm often happens, consult your service center
	OTU	PROCESSING_ERROR_ALARM	AUTOTEST_TEST_SYNCHRONIZATION	(1)	MAJOR	Test configured in database and in the OTU are not the same	Rebuild the OTU (dashboard->Configuration->Rebuild). If this alarm often happens, consult your service center
	PON	QUALITY_OF_SERVICE_ALARM	PON		MINOR, MAJOR	Peaks corresponding to PON termination are below the thresholds or not	Repair the fiber
SERVER	PROCESSING_ERROR_ALARM	CALENDAR_PROBLEM	(1)	MINOR	The calendar defined in the alert module is not correct (the events contain	Check your calendar	
SERVER	PROCESSING_ERROR_ALARM	ALARM_STORM	(1)	MINOR, MAJOR	Alarm storm	Consult your service center	
LINK	PROCESSING_ERROR_ALARM	HIGH_ALARM_RATE_TEST_UNSCHEDULED	(1)	MAJOR	Test is unscheduled due to high alarm rate	Check and update your test configuration	
SERVER	EQUIPMENT_ALARM	MEDIA_CONFIGURATION_PROBLEM	(1)	MINOR	Reaised if an error occurred during a media test	Check your media configuration	
SERVER	EQUIPMENT_ALARM	SNMP_SERVICE	(1)	MAJOR	Raised in case of SNMP configuration problem	Check your SNMP configuration	

(1) Free form text. Subject to change. Should not be processed.