

Root Cause Analysis Report



Report Date: 10/14/2024
Report Number: 16515
Revision: 0

IH SIFp- 80HSM: R3 Carrier Beam Near Miss 10.14.24

Problem Statement

Focal Point	R3 Delivery Carrier Beam fell into R3 Mill Pit onto Sled & Scaffold Platform			
When	Event Start Date:	10/14/2024	Event End Date:	10/14/2024
	Event Start Time:	1300	Event End Time:	1324
	Investigation Start Date:	10/14/2024	Investigation Start Time:	1301
	Unique Timing:	Start of Fall Outage- Mill Shutdown approximately 12 hours prior to incident		
Where	Business Unit:	80 HSM- Roughing Mill		
	Location:	3210 Watling St. East Chicago, IN 46312		
Actual Impact	Safety:	Damage to equipment, sled, carrier beam, scaffold platform		\$50,000.00
Potential Impact	Safety:	Serious Injury or Fatality to Team Members including Visiting Workers		

Solutions

- SO-0001 Incorporate design that prevents the carrier beams from raising into it's identified interference points
Status: Identified
- SO-0002 Incorporate carrier beam stops to prevent carrier beams from pbeing wedged on mill spreader and mill posts
Status: Identified
- SO-0003 Replace hydraulic isolation ball valves
Status: Identified
- SO-0004 P. Garza will test & tryout hydraulic isolation vavles for R1, R2, R4 & R5
Status: Identified
- SO-0005 J. Tessling will have existing keeper design modified to ensure contact with yoke if link is off center

Status: Identified

SO-0006 J. Tessling- Implement design to tie link arm together

Status: Identified

SO-0007 J. Tessling- Design & Implement means of blocking yoke in the up position

Status: Identified

SO-0008 Contact all HSM on LOTO requirements including accounting for stored energy

Status: Identified

Team

Nicole Hanas

